ASS. REC. BY: Marcus  REF: CS/FC	12300498844943
286	IGNMENT
286	The state of the s
DAG ACCIDENT PORT	L/Bal. 7 mm L/Bal. 7 mm
GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: days Res.: Yes or No	D.O.A. 1.2/05/23 D.O.I. 17/05/23
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS * &V1 (Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: £115 22787	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction De 7 12/c.	
- · · · · · · · · · · · · · · · · · · ·	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Final Penort	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fe	ee: : Site Insp (\$ )S+RS,SI
7	: Interview (\$ ) Photos
Report Format :	: Tech. Invs (\$ ) Others
Lump Sum / I.B.I: (\$	:Weekend (\$
,	TOTAL

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Owner ID Type:	Singapore NRIC
Owner ID:	8271
Vehicle Details	
Vehicle No.:	SML8417L
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2023
Vehicle Make:	KIA
Vehicle Model:	STONIC 1.0 DCT SR
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G3LCKP029952
Chassis No.:	KNAD6811VK6296645
Maximum Power Output:	88.3 kW (118 bhp)
Open Market Value:	\$18,863.00
Original Registration Date:	07 Jun 2019
First Registration Date:	07 Jun 2019
Transfer Count:	1
Actual ARF Paid:	\$8,863.00 443/
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2029
PARF Rebate Amount:	\$6,647.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$16,140.00
Total Rebate Amount:	\$22,787.00

The information contained herein is correct as at 17 May 2023

OK

## sgcarmart

Post an Ad

Q

8

New Cars Used Cars Car Loan Rental Cars Sell Cars Directory Products Insurance Articles Forum Resources

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Ways of Selling


Advertiser Login

Flexible Finance Solution by GV Cars Financing



\$0 Downpayment Available, Flexible In-House Loan at 3.28% by Gv Cars Financing. GV Automobile Centre StarAd







VW T-Cross goes up against the Kia Stonic

The T-Cross is more versatile and high-tech, while the Stonic is more approachable and delivers more driving thrills. Which entry-level crossover is better?

Read this article



Kia Stonic 1.0A EX

Posted: 09-May-2023

\$83,800

\$14,020 /yr

01-Feb-2019

998 cc

93,000 km

SUV

Available

Very well maintained by previous owner. Workshop check/STA evaluation can be arranged. Buy with a peace of mind. Viewing available.

Posted: 06-May-2023

Posted: 27-Apr-2023

Kia Stonic 1.0T SX Sunroof

\$78,800

\$12,850 /yr

06-Mar-2019

998 cc

81.000 km

SUV

Available

PREMIUM AD

PREMIUM AD

1 owner, fully agent serviced, 5 years agent warranty. Beautifully maintained by previous owner, excellent exterior and interior condition.

Compare

Kia Stonic 1.0T SX Sunroof

\$83,800

\$13,250 /yr

14-May-2019

998 cc

SUV

Available



# CYCLE & CARRIAGE KIA PTE LTD

### **Ubi Customer Service Centre**



330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666

#### **ESTIMATE**

o Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-)
Invoice Name & Address	THE THE STATE OF T	Owner Name & Vehicle Info
	Cust No/Name	/Mr Jin Zhenguo
MS First Capital Insurance Ltd	Reg No/Reg Date	SML8417L / 07/06/2019
16 Raffles Quay	Date In/Mileage	
#42-01 Hong Leong Building	Chassis No	KNAD6811VK6296645
Singapore 048581	Engine No	G3LCKP029952
Contact No	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
33,1223, 113	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		A Court	WIP No		SHAP LINES AT
CTP00080	Cash	15/05/2023/ 16:15	LER	972 / Ma	rs Ler		19520		
7 PER - SERVICE	The same	Description of Goods	/ Services		DEX 1	Qty	Unit Price Disc	% A	mount
	AIMING T	<mark>5/2023 A</mark> LONG LOYANG A HIRD PARTY MENT CAR	VE						
TP # YQ7	978Y	TP INS: MS FIRST CAP	PITAL				50	2	50.00
REAR NUM M SUNDRY	BER PLAT	E WITH CASING					ne	1	50.00
C&C BADG	E						80		160.00
	SEALANT	KIT ON NEW PANEL	_Д			7	10		200.00
	ANTI-CO	RROSION ON REAR ACCID	ENT AFFEC	TED AREAS		11(=	7 su		-280.00
E PNT88000 TO INSTA	LL RIKEC	OOL SOLAR FILM ON TAI	LGATE GLA	SS L					320.00
E PNT88000		ATE GLASS					ne		80.00
M SUNDRY		AILGATE GLASS					. 1 (87.849.57)		
E DNITOROOO		GATE COMPONENT AND ME	CHANISM P	ART			3 5	4	640.00
- DUTOCOOO					١٧		11	×	640.00
TO REMOV	E AND RE EPAIR ON	INSTALL TRIMMING AND REAR ACCIDENT AFFECT	ED AREAS	10 dive w	N. S.				100.00
F PNT88000		T REVERSE SENSOR					120		2560.00
E PNT88000 TO REPLA	CE TAILG	ATE PNL,REAR BUMPER,F	REINFORCEM	ENT,ETC	640		1250		2300.00
TO DEDA	TO OFAD	END PANEL M,ALIGN ON REAR ACCIO			560		1100		2200.00
E DUTOCOOO		N REAR ACCIDENT AFFEC					V		280.00
A 10028901							-		arc-ent/07/2/200686

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced, occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. Page 1 of 3



## CYCLE & CARRIAGE KIA PTE LTD

#### **Ubi Customer Service Centre**



330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666

Co Reg No : 199405410K

#### **ESTIMATE**

		G	ST	Reg	No	:	MR-8500111-X
lar	ne &	Vehic	le	Info			100
Mr	Jin	Zheng	juc	)			
	/ (	07/06/	/20	19			
3/	6	1171					
VE	2066	15					

invoice Name & Address	A CONTRACTOR	Owner Name & Venicle Info		
MS First Capital Insurance Ltd	Cust No/Name	/Mr Jin Zhenguo		
	Reg No/Reg Date	SML8417L / 07/06/2019		
16 Raffles Quay	Date In/Mileage	15/05/2023/ 61171		
#42-01 Hong Leong Building Singapore 048581	Chassis No	KNAD6811VK6296645		
3111gapore 046361	Engine No	G3LCKP029952		
Contact No	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF			
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK		

Account No	Terms	Date/Tim	e Printed		CSE	Ope	rator		y extent	WIP No		Part in	1 1
CTP00080	Cash	15/05/20	023/ 16:1	15	LER	972	/ Mars	Ler		19520			
4 (7)	ALL LINES	Descrip	tion of Go	ods /	Services	5 HOTEL	770	9.14	Qty	<b>Unit Price</b>	Disc%	A	mount
TO CONDU	CT DIAGN	OSTIC CHE	CK BY KD	S AND	CLEAR T	ROUBLE	CODE						
A 90000001	RING & F	LECTRICAL	CVCTEM							•	fo		100.00
M SUNDRY		LLUTRICAL	3131611							3	20		50.00
SUNDRIES				020									
M PANEL AS	SY-TAIL	GATE	rods A	9					1.00	1530.00	00.00		1530.00
M LATCH AS	SY-TAIL	GATE	8 873						1.00	106.00	00.00	?	106.0
M LOGO ASS	Y-KIA SU	В	nu						1.00	61.00	00.00	_	61.0
M EMBLEM-S	TONIC		nu						1.00	26.00	00.00	_	26.00
M EMBLEM-T	URBO G.D	. I	Me						1.00	38.00	00.00		38.00
M W/STRIP-	TAIL GAT	E OPNG	1w						□1.00	91.00	00.00		91.00
M LAMP ASS	Y-LICENS	E PLATE		6	245	D PS	3	(	5 2.00	119.00	00.00		238.00
		K LID HDL	ASSY	6	511		111	7	1.00	758.00	00.00	?	758.0
M GLASS AS	SY-TAIL	GATE	nu	10	7 6	ЦЦ	$\sqcup \sqcup$	(9)	(4.b)	395.00	00.00	_	395.0
M CLIP			nes						8.00			-	40.0
M GARNISH-	T/GATE U	PR,RH							1.00	66.00	00.00	7	66.0
M GARNISH-	T/GATE U	PR,LH							1.00	66.00	00.00	7	66.00
M COVER-RR	BUMPER	LWR	300						1.00	385.00	00.00	_	385.0
M MOULDING	ASSY-RR	BUMPER S	IDE, LH	20					1.00	209.00	00.00		209.00
M MOULDING	ASSY-RR	BUMPER S	IDE, RH	20					1.00	152.00	00.00		152.00
M SKID PLA	TE-RR BU	MPER	30	501					1.00	122.00	00.00		122.00
M ULTRASON	IC SENSO	R ASSY-BW	S						2.00	189.00	00.00	?	378.00
M LAMP ASS	Y-REAR F	OG & R/RE	FL,LH						1.00	175.00	00.00	2	175.00
M LAMP ASS	Y-REAR F	OG & R/RE	FL,RH						1.00	127.00	00.00	7	127.00
M BEAM-RR	BUMPER								1.00	419.00	00.00	_	419.00
M BRACKET-	RR BEAM	LWR MTG,L	Н						1.00		00.00	2	7.00
M BRACKET-	RR BEAM	LWR MTG,R	Н						1.00	5.00	00.00	2	5.00
M BRACKET-	RR BEAM	UPR MTG							1.00		00.00	_	9.00
M STAY-RR	BUMPER L	Н							1.00		00.00		55.00
M STAY-RR	BUMPER R	Н							1.00	76.00	00.00	2	76.00
M BRACKET-	RR BEAM	UPR MTG	500						2.00		00.00	,	18.00
M CAP-RR H	00K		>//	C					1.00		00.00		5.00
M BRACKET	ASSY-RR	RUMPER STI	DF . I H						1.00	27.00	00.00		27.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



#### **CYCLE & CARRIAGE KIA PTE LTD**

#### **Ubi Customer Service Centre**



330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666

Co Reg No : 199405410K

Authorized signatory and company stamp

#### **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
MS First Capital Insurance Ltd	Cust No/Name	/Mr Jin Zhenguo			
no instructional insurance Ltu	Reg No/Reg Date	SML8417L / 07/06/201 9			
16 Raffles Quay #42-01 Hong Leong Building	Date In/Mileage	15/05/2023/ 61171			
	Chassis No	KNAD6811VK6296645			
Singapore 048581	Engine No	G3LCKP029952			
Contact No	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF			
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK			

				Colour/Irin	ABI PLATIN	UM GRAPHI/	WK SATURI	DLACK
Account N	o Terms	Date/Time Printed	CSE	Operator		WIP No		
CTP00080	Cash	15/05/2023/ 16:15	LER	972 / Mars	Ler	19520		
of the last		Description of Goods	/ Services		Qty	Unit Price	Disc%	Amount
M BRACKE M CLIP	T ASSY-RR	BUMPER SIDE,RH			1.00 10.00		00.00	27.00 10.00
			ST.	AME: _ME	ate Andre	ul		
		D. D	URVEYOR SI ATE : EMARKS : _	17/5/ 7-h p	123 0 10.	lvan party		
		LKK Auto Consultants he the Repairer of the follow To resurvey before/after spra To display damaged part(s) Parts prices are subject to e	y painting	y" hacis				
Confirm 8	accepted	Parts prices are subject to e     Third party survey is on a "V     No illegal modification(s) is     Supplementary item(s) mus is subject to final approval f	ha sosupieved	and	8% GST on	Net 13331.0		13,331.00 1066.48
		Acknowledged by Repairer			Te	otal Payabl	e	14,397.48

Validity of this estimate is—14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.