

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ FC123004986/Uny3

## ASSIGNMENT

From: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_

Date: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SML8417Cat Workshop m/s C&C 10.30

of \_\_\_\_\_

Insured: YQ7978Y

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$78k.

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 6 days

Res.: Yes or No

Lum Sum: 1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: LIA 22787Veh No: SML8417CYr Regn: 07/06/19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: KIA Stonic

c.c

998Colour: GreyA/C: Insured / Std / NI / NASp. Reading: 61432T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNF-D6811V-K6296645Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 7 mmR/Bal. 3 mmL/Bal. 7 mmL/Bal. 3 mmD.O.A. 12/05/23D.O.I. 17/05/23

Survey held at \_\_\_\_\_

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Def 12k.

3.15/23 P17 @ ~~\$488.80~~ : Inform Mars per  
\$7860 (Red. \$5471.41%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 6

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ S + RS, \_\_\_\_ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	827I
<b>Vehicle Details</b>	
Vehicle No.:	SML8417L
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2023
Vehicle Make:	KIA
Vehicle Model:	STONIC 1.0 DCT SR
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G3LCKP029952
Chassis No.:	KNAD6811VK6296645
Maximum Power Output:	88.3 kW (118 bhp)
Open Market Value:	\$18,863.00
Original Registration Date:	07 Jun 2019
First Registration Date:	07 Jun 2019
Transfer Count:	1
Actual ARF Paid:	\$8,863.00 443 /
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2029
PARF Rebate Amount:	\$6,647.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	06 Jun 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$16,140.00
<b>Total Rebate Amount:</b>	<b>\$22,787.00</b>

The information contained herein is correct as at 17 May 2023

OK



New Cars   Used Cars   Car Loan   Rental Cars   Sell Cars   Directory   Products   Insurance   Articles   Forum   Resources

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)   [Advertiser Login](#)   [Ways of Selling](#)

**Flexible Finance Solution by GV Cars Financing**



\$0 Downpayment Available,  
Flexible In-House Loan at 3.28%  
by Gv Cars Financing.  
GV Automobile Centre   StarAd

**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997**   [view our cars](#)

Sort by Date Posted 20 results/page

11 vehicles



Kia Stonic

Any Category

Advanced Search

Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Stonic	Any	Any	2019	Any	Any	Any	Available
	Kia Stonic 1.0T EX	\$84,800	\$12,840 /yr	05-Sep-2019	998 cc	40,000 km	SUV	Available
New Arrival with Sporty Outlook! 1 Owner Unit With Low Mileage Clocked! Showroom Condition. Vehicle Fully Maintained At Agent C&C... Posted: 15-May-2023								
	Kia Stonic 1.0T SX Sunroof	\$77,800	\$12,750 /yr	20-Feb-2019	998 cc	79,000 km	SUV	Available
\$0 Admin Fees. Zero Down-payment. Definitely The Best Conditioned Unit In The Market. View To Appreciate. Buy With A Peace Of Min... Posted: 14-May-2023								
	Kia Stonic 1.0T EX	\$78,000	\$12,900 /yr	20-Feb-2019	998 cc	32,000 km	SUV	Available
1 lady owner unit, lowest mileage, well kept and in good condition, maintained by C&C, flexible loan, please call or WhatsApp for viewing. Posted: 10-May-2023								
	Kia Stonic 1.0T SX Sunroof	\$88,800	\$13,350 /yr	03-Sep-2019	998 cc	35,000 km	SUV	Available
C&C maintained. SX Sunroof model, 5 years warranty by C&C! Timely serviced with agent! Like brand new! Low mileage! Accident free!... Posted: 09-May-2023								
	<b>VW T-Cross goes up against the Kia Stonic</b> The T-Cross is more versatile and high-tech, while the Stonic is more approachable and delivers more driving thrills. Which entry-level crossover is better? <a href="#">Read this article</a>							
	Kia Stonic 1.0A EX	\$83,800	\$14,020 /yr	01-Feb-2019	998 cc	93,000 km	SUV	Available
Very well maintained by previous owner. Workshop check/STA evaluation can be arranged. Buy with a peace of mind. Viewing available... Posted: 06-May-2023								
	Kia Stonic 1.0T SX Sunroof	\$78,800	\$12,850 /yr	06-Mar-2019	998 cc	81,000 km	SUV	Available
1 owner, fully agent serviced, 5 years agent warranty. Beautifully maintained by previous owner, excellent exterior and interior condition... Posted: 27-Apr-2023								
Compare	Kia Stonic 1.0T SX Sunroof	\$83,800	\$13,250 /yr	14-May-2019	998 cc	-	SUV	Available



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Ltd	Cust No/Name /Mr Jin Zhenguo
16 Raffles Quay	Reg No/Reg Date SML8417L / 07/06/2019
#42-01 Hong Leong Building	Date In/Mileage 15/05/2023/ 61171
Singapore 048581	Chassis No KNAD681VK6296645
Contact No	Engine No G3LCKP029952
	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	15/05/2023/ 16:15	LER	972 / Mars Ler	19520			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 12/05/2023 ALONG LOYANG AVE								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT CAR								
TP # YQ7978Y TP INS: MS FIRST CAPITAL								
E PNT88000						502		50.00
REAR NUMBER PLATE WITH CASING								
M SUNDRY						nm		50.00
C&C BADGE								
M SUNDRY						80		160.00
TO APPLY SEALANT KIT ON NEW PANEL								
M SUNDRY						100		200.00
TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000						nm		280.00
TO INSTALL RIKECOOL SOLAR FILM ON TAILGATE GLASS								
E PNT88000								320.00
TO REPLACE TAILGATE GLASS								
M SUNDRY						nm		80.00
SEALANT KIT ON TAILGATE GLASS								
E PNT88000						320		640.00
TO TRANSFER TAILGATE COMPONENT AND MECHANISM PART								
E PNT88000						11	X	640.00
TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY								
ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								100.00
TO CHECK AND TEST REVERSE SENSOR								
E PNT88000						1280		2560.00
TO REPLACE TAILGATE PNL,REAR BUMPER,REINFORCEMENT,ETC					640			
-TO REPAIR REAR END PANEL								
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					580			
E PNT98000						1650		2200.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
A 10028901								280.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Ltd	Cust No/Name /Mr Jin Zhenguo
16 Raffles Quay	Reg No/Reg Date SML8417L / 07/06/2019
#42-01 Hong Leong Building	Date In/Mileage 15/05/2023/ 61171
Singapore 048581	Chassis No KNAD6811VK6296645
Contact No	Engine No G3LCKPC29952
	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	15/05/2023/ 16:15	LER	972 / Mars Ler	19520

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE				
A 90000001				100.00
CHECK WIRING & ELECTRICAL SYSTEM				
M SUNDRY				50.00
SUNDRIES				
M PANEL ASSY-TAIL GATE	1.00	1530.00	00.00	1530.00
M LATCH ASSY-TAIL GATE	1.00	106.00	00.00	106.00
M LOGO ASSY-KIA SUB	1.00	61.00	00.00	61.00
M EMBLEM-STONIC	1.00	26.00	00.00	26.00
M EMBLEM-TURBO G.D.I	1.00	38.00	00.00	38.00
M W/STRIP-TAIL GATE OPNG	1.00	91.00	00.00	91.00
M LAMP ASSY-LICENSE PLATE	2.00	119.00	00.00	238.00
M RR CAMERA & TRUNK LID HDL ASSY	1.00	758.00	00.00	758.00
M GLASS ASSY-TAIL GATE	1.00	395.00	00.00	395.00
M CLIP	8.00	5.00	00.00	40.00
M GARNISH-T/GATE UPR,RH	1.00	66.00	00.00	66.00
M GARNISH-T/GATE UPR,LH	1.00	66.00	00.00	66.00
M COVER-RR BUMPER LWR	1.00	385.00	00.00	385.00
M MOULDING ASSY-RR BUMPER SIDE,LH	1.00	209.00	00.00	209.00
M MOULDING ASSY-RR BUMPER SIDE,RH	1.00	152.00	00.00	152.00
M SKID PLATE-RR BUMPER	1.00	122.00	00.00	122.00
M ULTRASONIC SENSOR ASSY-BWS	2.00	189.00	00.00	378.00
M LAMP ASSY-REAR FOG & R/REFL,LH	1.00	175.00	00.00	175.00
M LAMP ASSY-REAR FOG & R/REFL,RH	1.00	127.00	00.00	127.00
M BEAM-RR BUMPER	1.00	419.00	00.00	419.00
M BRACKET-RR BEAM LWR MTG,LH	1.00	7.00	00.00	7.00
M BRACKET-RR BEAM LWR MTG,RH	1.00	5.00	00.00	5.00
M BRACKET-RR BEAM UPR MTG	1.00	9.00	00.00	9.00
M STAY-RR BUMPER LH	1.00	55.00	00.00	55.00
M STAY-RR BUMPER RH	1.00	76.00	00.00	76.00
M BRACKET-RR BEAM UPR MTG	2.00	9.00	00.00	18.00
M CAP-RR HOOK	1.00	5.00	00.00	5.00
M BRACKET ASSY-RR BUMPER SIDE,LH	1.00	27.00	00.00	27.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Ltd	Cust No/Name /Mr Jin Zhenguo
16 Raffles Quay	Reg No/Reg Date SML8417L / 07/06/2019
#42-01 Hong Leong Building	Date In/Mileage 15/05/2023/ 61171
Singapore 048581	Chassis No KNAD6311VK6296645
Contact No	Engine No G3LCKP029952
	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CTP00080	Cash	15/05/2023/ 16:15	LER	972 / Mars Ler	19520				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M	BRACKET ASSY-RR BUMPER SIDE,RH			11	1	00	27.00	00.00	27.00
M	CLIP			11	10	00	1.00	00.00	10.00

# Estimate

*W F Ardund*

SURVEYOR NAME: *Mars Ler*

SURVEYOR SIGNATURE: \_\_\_\_\_

DATE: *17/5/23 @ 10.10am*

REMARKS: *7th ph. Super car,*

*6471*

*p/p \$2488.80*

Confirm & accepted by


- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged parts during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

8% GST on	Nett 13,331.00	13,331.00
		1066.48
	<b>Total Payable</b>	<b>14,397.48</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 63661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581  Contact No 26/05/	Cust No/Name /Mr Jin Zhenguo Reg No/Reg Date SML8417L / 07/06/2019 Date In/Mileage 22/05/2023/ 61171 Chassis No KNAD68.1VK6296645 Engine No G3LCKP029952 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	29/05/2023/ 11:19	LER	972 / Mars Ler	19520			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 12/05/2023 ALONG LOYANG AVE								
OWNER CLAIMING THIRD PARTY								
LOSS OF USE AND LOSS OF RENTAL								
TP # YQ7978Y TP INS: MS FIRST CAPITAL								
E PNT88000								50.00
REAR NUMBER PLATE WITH CASING								
M SUNDRY								50.00
C&C BADGE								
M SUNDRY								80.00
TO APPLY SEALANT KIT ON NEW PANEL								
M SUNDRY								100.00
TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								280.00
TO INSTALL RIKECOOL SOLAR FILM ON TAILGATE GLASS								
E PNT88000								320.00
TO REPLACE TAILGATE GLASS								
M SUNDRY								80.00
SEALANT KIT ON TAILGATE GLASS								
E PNT88000								320.00
TO TRANSFER TAILGATE COMPONENT AND MECHANISM PART								
E PNT88000								100.00
TO CHECK AND TEST REVERSE SENSOR								
E PNT88000								1280.00
TO REPLACE TAILGATE PNL,REAR BUMPER,REINFORCEMENT,ETC								
-TO REPAIR REAR END PANEL								
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
E PNT98000								1650.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
A 10028901								280.00
TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE								
A 90000001								80.00
CHECK WIRING & ELECTRICAL SYSTEM								

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 63661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Ltd	Cust No/Name /Mr Jin Zhenguo
16 Raffles Quay	Reg No/Reg Date SML8417L / 07/06/2019
#42-01 Hong Leong Building	Date In/Mileage 22/05/2023/ 61171
Singapore 048581	Chassis No KNAD681VK6296645
Contact No	Engine No G3LCKP029952
26/05/	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	29/05/2023/ 11:19	LER	972 / Mars Ler	19520

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY				20.00
SUNDRIES				
X PANEL ASSY-TAIL GATE	1.00	1530.00	00.00	1530.00
X LATCH ASSY-TAIL GATE	1.00	106.00	00.00	106.00
X LOGO ASSY-KIA SUB	1.00	61.00	00.00	61.00
X EMBLEM-STONIC	1.00	26.00	00.00	26.00
X EMBLEM-TURBO G.D.I	1.00	38.00	00.00	38.00
X W/STRIP-TAIL GATE OPNG	1.00	91.00	00.00	91.00
X GLASS ASSY-TAIL GATE	1.00	395.00	00.00	395.00
M CLIP	8.00	5.00	00.00	40.00
X COVER-RR BUMPER LWR	1.00	385.00	00.00	385.00
X MOULDING ASSY-RR BUMPER SIDE,LH	1.00	209.00	00.00	209.00
X MOULDING ASSY-RR BUMPER SIDE,RH	1.00	152.00	00.00	152.00
X SKID PLATE-RR BUMPER	1.00	122.00	00.00	122.00
X CAP-RR HOOK	1.00	5.00	00.00	5.00
X CLIP	10.00	1.00	00.00	10.00

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

8% GST on      Net      7,860.00  
                          7860.00      628.80  
 Total Payable      8,488.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.