

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|--------------------------------|--|
| MS First Capital Insurance Ltd | Cust No/Name /Mr Jin Zhenguo |
| 16 Raffles Quay | Reg No/Reg Date SML8417L / 07/06/2019 |
| #42-01 Hong Leong Building | Date In/Mileage 22/05/2023/ 61171 |
| Singapore 048581 | Chassis No KNAD6811VK6296645 |
| Contact No | Engine No G3LCKP029952 |
| 26/05/ | Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF |
| | Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---|-------|-------------------|-----|----------------|-----------------------------|
| CTP00080 | Cash | 29/05/2023/ 11:19 | LER | 972 / Mars Ler | 19520 |
| Description of Goods / Services | | | | | Qty Unit Price Disc% Amount |
| Z TEXT | | | | | |
| ACCIDENT ON 12/05/2023 ALONG LOYANG AVE | | | | | |
| OWNER CLAIMING THIRD PARTY | | | | | |
| LOSS OF USE AND LOSS OF RENTAL | | | | | |
| TP # YQ7978Y TP INS: MS FIRST CAPITAL | | | | | |
| E PNT88000 | | | | | 50.00 |
| REAR NUMBER PLATE WITH CASING | | | | | |
| M SUNDRY | | | | | 50.00 |
| C&C BADGE | | | | | |
| M SUNDRY | | | | | 80.00 |
| TO APPLY SEALANT KIT ON NEW PANEL | | | | | |
| M SUNDRY | | | | | 100.00 |
| TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS | | | | | |
| E PNT88000 | | | | | 280.00 |
| TO INSTALL RIKECOOL SOLAR FILM ON TAILGATE GLASS | | | | | |
| E PNT88000 | | | | | 320.00 |
| TO REPLACE TAILGATE GLASS | | | | | |
| M SUNDRY | | | | | 80.00 |
| SEALANT KIT ON TAILGATE GLASS | | | | | |
| E PNT88000 | | | | | 320.00 |
| TO TRANSFER TAILGATE COMPONENT AND MECHANISM PART | | | | | |
| E PNT88000 | | | | | 100.00 |
| TO CHECK AND TEST REVERSE SENSOR | | | | | |
| E PNT88000 | | | | | 1280.00 |
| TO REPLACE TAILGATE PNL, REAR BUMPER, REINFORCEMENT, ETC | | | | | |
| -TO REPAIR REAR END PANEL | | | | | |
| STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS | | | | | |
| E PNT98000 | | | | | 1650.00 |
| SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS | | | | | |
| A 10028901 | | | | | 280.00 |
| TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE | | | | | |
| A 90000001 | | | | | 80.00 |
| CHECK WIRING & ELECTRICAL SYSTEM | | | | | |

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

CYCLE & CARRIAGE

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|--------------------------------------|
| MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Contact No 26/05/ | Cust No/Name | /Mr Jin Zhenguo |
| | Reg No/Reg Date | SML8417L / 07/06/2019 |
| | Date In/Mileage | 22/05/2023/ 61171 |
| | Chassis No | KNAD6811VK6296645 |
| | Engine No | G3LCKP029952 |
| | Make/Model | KIA/STONIC 1.0 A SX BJ3 W SUNROOF |
| | Colour/Trim | ABT PLATINUM GRAPHI/ WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|---------------------------------|---------------------------------|-------------------|-----|----------------|------------|-------|---------|
| CTP00080 | Cash | 29/05/2023/ 11:19 | LER | 972 / Mars Ler | 19520 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| M SUNDRY | | | | | | | 20.00 |
| SUNDRIES | | | | | | | |
| X | PANEL ASSY-TAIL GATE | | | 1.00 | 1530.00 | 00.00 | 1530.00 |
| X | LATCH ASSY-TAIL GATE | | | 1.00 | 106.00 | 00.00 | 106.00 |
| X | LOGO ASSY-KIA SUB | | | 1.00 | 61.00 | 00.00 | 61.00 |
| X | EMBLEM-STONIC | | | 1.00 | 26.00 | 00.00 | 26.00 |
| X | EMBLEM-TURBO G.D.I | | | 1.00 | 38.00 | 00.00 | 38.00 |
| X | W/STRIP-TAIL GATE OPNG | | | 1.00 | 91.00 | 00.00 | 91.00 |
| X | GLASS ASSY-TAIL GATE | | | 1.00 | 395.00 | 00.00 | 395.00 |
| M | CLIP | | | 8.00 | 5.00 | 00.00 | 40.00 |
| X | COVER-RR BUMPER LWR | | | 1.00 | 385.00 | 00.00 | 385.00 |
| X | MOULDING ASSY-RR BUMPER SIDE,LH | | | 1.00 | 209.00 | 00.00 | 209.00 |
| X | MOULDING ASSY-RR BUMPER SIDE,RH | | | 1.00 | 152.00 | 00.00 | 152.00 |
| X | SKID PLATE-RR BUMPER | | | 1.00 | 122.00 | 00.00 | 122.00 |
| X | CAP-RR HOOK | | | 1.00 | 5.00 | 00.00 | 5.00 |
| X | CLIP | | | 10.00 | 1.00 | 00.00 | 10.00 |

Confirm & accepted by

8% GST on **Nett** **7,860.00**
628.80
Total Payable **8,488.80**

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.