



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
T K MOTOR WORKSHOP		Ref:	CS/TP23004988/Aqp3e2
BLK 1 KAKI BUKIT AVE 6 #02-56SINGAPORE 417883		Date:	21/07/2023
ON BEHALF OF KARTHIKESHAVAN S/O GOVINDAN		Code:	TP179
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SNC 3985G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/04/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2054402F465953	Colour	WHITE
Odometer	98221 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	HABILEAD	6 mm
L/H Front Tyre	245/40 R18	HABILEAD	6 mm
R/H Rear Tyre	245/40 R18	HABILEAD	6 mm
L/H Rear Tyre	245/40 R18	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/04/2023	Inspection Date	19/04/2023
Survey held at	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	