

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO. : 53049097-L

KARTHIKEVASHAN S/O GOVINDAN
8 KENG CHIN ROAD #12-15
SINGAPORE 258710

DATE : 08/05/2023

ACCIDENT DATE : 30/04/2023
MODEL : MERCEDES BENZ / C180 CONVERTIBLE (R17 LED)
CHASSIS NO. : WDD2054402F465953

ESTIMATE COST OF REPAIRS TO MERCEDES BENZ CAR NO. : SNC3985G

1 PC FRONT R/H FENDER <i>Dented.</i>	S \$ 952.00 NETT ✓
1 PC FRONT R/H HEADLAMP <i>lt.</i>	\$ 3,300.00 NETT ✓
1 PC FRONT CENTRE HEADLAMP SUPPORT RETAINER <i>Dmg d</i>	\$ 312.00 NETT ✓
1 PC FRONT R/H HEADLAMP LOWER BRACKET <i>crackd.</i>	\$ 96.00 NETT ✓
1 PC FRONT GRILLE (DIAMOND VERSION GRILLE) <i>crackd</i>	\$ 998.00 NETT ✓
6 PC FRONT GRILLE CLIP <i>new</i>	\$ 30.00 NETT ✓
1 PC FRONT GRILLE EMBLEM <i>new new</i>	\$ 298.00 NETT ✓
1 PC FRONT GRILLE INNER BASE GARNISH <i>Defund</i>	\$ 412.00 NETT ✓
1 PC FRONT BUMPER <i>Defund.</i>	\$ 1,690.00 NETT ✓
2 PC FRONT BUMPER SIDE RETAINER <i>2H Dmg d</i>	\$ 76.00 NETT <i>38</i> ✓
8 PC FRONT BUMPER CLIP <i>mv</i>	\$ 60.00 NETT ✓
2 PC FRONT BUMPER R/H PARKING SENSOR <i>1 piece dmg d</i>	\$ 624.00 NETT <i>312</i> ✓
1 PC FRONT BUMPER R/H SIDE GARNISH <i>crackd</i>	\$ 168.00 NETT ✓
1 PC FRONT BUMPER TOP SUPPORT GARNISH <i>new</i>	\$ 212.00 NETT ✓
1 PC FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>	\$ 726.00 NETT ✓
1 PC FRONT BUMPER SPONGE <i>crackd</i>	\$ 196.00 NETT ✓
1 PC FRONT R/H 18 INCH SPORT RIM <i>lt.</i>	\$ 1,860.00 NETT <i>1200 (sw)</i> ✓
1 PC FRONT R/H TYRE (235/40/R18) <i>new</i>	\$ 650.00 S/NETT ✓
2 PC FRONT R/H LOWER ARM <i>Best</i>	\$ 898.00 NETT ✓
1 PC FRONT R/H KNUCKLE ARM <i>damaged</i>	\$ 856.00 NETT ✓
1 PC FRONT R/H KNUCKLE HUP <i>damaged</i>	\$ 568.00 NETT ✓

1 PC FRONT R/H KNUCKLE HUP BEARING *and* \$ 312.00 NETT ✓
 1 PC FRONT R/H SHOCK ABSORBER *but* \$ 986.00 NETT ✓

12910 S.N: 12W
 11619

LABOUR CHARGE

TO SPRAY PAINTING \$ ~~750.00~~ 500
 TO CHECK WIRING \$ 50.00 ✓
 LABOUR CHARGE TO PANEL BEATING , WELDING , REMOVING
 ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC. \$ ~~680.00~~ 600
 TO COMPUTER WHEEL ALIGNMENT \$ ~~90.00~~ 80
 TO REMOVE & REFIX FRONT UNDERCARRIAGE \$ ~~380.00~~ 250
 TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK \$ ~~180.00~~ 120
 TO MEASURE, DRILL & REINSTALL THE REPLACED FRONT
 BUMPER POSITION & REINSTALL FRONT PARKING SENSOR
 ,CONTROL UNTIL , CHECK & TEST FOR FUNCTIONING 1710 \$ 120.00 50
 TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED
 PANEL FOR RUST PROTECTION \$ 80.00 60

TOTAL : \$ \$18,610.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 14525

(P/P)

06 Days.

TK MOTOR WORKSHOP

