



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC23004991/Kwy3e2 Date: 08/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 9996L	Veh. Inspected	SLM 414D
	Policy No.	z22vc05014442	Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/027400	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	16/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MR053REH104559152	Colour	METALLIC GREY
	Odometer	123777 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	MICHELIN	4 mm
	L/H Front Tyre	215/45 R17	MICHELIN	4 mm
	R/H Rear Tyre	215/45 R17	MICHELIN	3 mm
	L/H Rear Tyre	215/45 R17	MICHELIN	3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/05/2023	Inspection Date	16/05/2023
	Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	