

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ABSOLUTE TECH PTE LTD
 64C PAGODA STREET
 SINGAPORE 059223

Contact : 91453949

TAX INVOICE *TPECICS.*

Repair Code : CLM17761

Date in : 13/05/2023

Xiao Chan.

Vehicle Num. : SLU5536K

Model : MINI COOPER S CLUBMAN AT LED NAV

Chassis/Eng# : WMWLN720402G78713/F329H554B48A20A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delhd</i>	1	1080.00	✓ 1,080.00
REAR BUMPER CENTER BRACKET L/R <i>ambd</i>	2	180.00	✓ 360.00
REAR BUMPER KEYLESS SENSOR <i>ambd</i>	1	1450.00	✓ 1,450.00
REAR BUMPER LEG KICK SENSOR (LOWER) <i>gnd</i>	1	62.00	✓ 62.00
REAR BUMPER LEG KICK SENSOR (TOP)	1	55.00	✓ 55.00
REAR BUMPER LEG KICK SENSOR BRACKET <i>ambd</i>	1	60.00	✓ 60.00
REAR BUMPER LEG KICK SENSOR MODULE <i>ambd</i>	1	550.00	✓ 550.00
REAR BUMPER LOWER BRACKET L/R <i>new</i>	2	45.00	✓ 90.00
REAR BUMPER LOWER LID <i>Delhd</i>	1	260.00	✓ 260.00
REAR BUMPER NUMBER PLATE LAMP L/R <i>ambd</i>	2	38.00	✓ 76.00
REAR BUMPER REFLECTOR LAMP L/R <i>ambd</i>	2	170.00	✓ 340.00
REAR BUMPER REINFORCEMENT <i>Delhd</i>	1	550.00	✓ 550.00
REAR BUMPER REVERSE CAMERA <i>ambd</i>	1	720.00	✓ 720.00
REAR BUMPER REVERSE SENSOR <i>2 pieces dngd</i>	4	280.00	560.00 ✓ 1,120.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	2	55.00	✓ 110.00
REAR BUMPER REVERSE SENSOR O-RING <i>new</i>	4	18.00	✓ 72.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	350.00	✓ 350.00
REAR BUMPER SPONGE L/R <i>ambd</i>	2	60.00	✓ 120.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ABSOLUTE TECH PTE LTD
 64C PAGODA STREET
 SINGAPORE 059223

Contact : 91453949

TAX INVOICE

Repair Code : CLM17761

Date in : 13/05/2023

Vehicle Num. : SLU5536K

Model : MINI COOPER S CLUBMAN AT LED NAV

Chassis/Eng# : WMWLN720402G78713/F329H554B48A20A

REAR BUMPER TOW HOOK COVER L/R	<i>LH rhd!</i>	2	49.00	<i>49</i>	98.00
REAR END PANEL	<i>Dented</i>	1	410.00	<i>/</i>	410.00
REAR END PANEL INNER TOP GARNISH	<i>Dented</i>	1	110.00	<i>/</i>	110.00
REAR EXHAUST SILENCER BOX	<i>Dented</i>	1	1200.00	<i>1090</i>	1200.00
REAR EXHAUST SILENCER HEAT COVER (TOP)	<i>tom</i>	1	85.00	<i>/</i>	85.00
REAR EXHAUST SILENCER HEAT COVER (VERTICAL)	<i>tom</i>	1	85.00	<i>/</i>	85.00
REAR EXHAUST SILENCER RUBBER MOUNTING	<i>neu</i>	2	27.00	<i>+</i>	54.00
REAR FLOOR BOARD COVER	<i>Dented</i>	1	130.00	<i>/</i>	130.00
REAR FLOOR SIDE COVER	<i>neu</i>	1	55.00	<i>+</i>	55.00
REAR FLOOR TOP BOARD COVER	<i>neu</i>	1	410.00	<i>+</i>	410.00
REAR LH TAILGATE	<i>Dented</i>	1	300.00	<i>700</i>	300.00
REAR LH TAILGATE EMBLEM CLUBMAN	<i>neu</i>	1	72.00	<i>/</i>	72.00
REAR LH TAILGATE EMBLEM MINI LOGO	<i>neu</i>	1	70.00	<i>/</i>	70.00
REAR LH TAILGATE INNER TRIM BOARD	<i>cond</i>	1	165.00	<i>/</i>	165.00
REAR LH TAILGATE MECHANISM LOCK	<i>neu</i>	1	138.00	<i>/</i>	138.00
REAR LH TAILGATE OUTER CHROME HANDLE	<i>neu</i>	1	140.00	<i>+</i>	140.00
REAR LH TAILGATE WEATHER STRIP VERTICAL	<i>at</i>	1	168.10	<i>/</i>	168.10
REAR LH TAILGATE WINDSCREEN MOULDING	<i>neu</i>	1	255.00	<i>/</i>	255.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ABSOLUTE TECH PTE LTD
 64C PAGODA STREET
 SINGAPORE 059223

Contact : 91453949

TAX INVOICE

Repair Code : CLM17761
 Date in : 13/05/2023
 Vehicle Num. : SLU5536K
 Model : MINI COOPER S CLUBMAN AT LED NAV
 Chassis/Eng# : WMWLN720402G78713/F329H554B48A20A

REAR RH TAILGATE	<i>Repis</i>	1	700.00	<i>+</i>	700.00
REAR RH TAILGATE 'COOPER S' EMBLEM	<i>me</i>	1	65.00	<i>-</i>	65.00
REAR RH TAILGATE INNER TRIM BOARD	<i>me</i>	1	155.00	<i>+</i>	155.00
REAR RH TAILGATE MECHANISM LOCK	<i>dem</i>	1	130.00	<i>+</i>	130.00
REAR RH TAILGATE OUTER CHROME HANDLE	<i>me</i>	1	140.00	<i>+</i>	140.00
REAR RH TAILGATE WINDSCREEN MOULDING	<i>me</i>	1	255.00	<i>+</i>	255.00
REAR TAILGATE INNER WEATHER STRIP	<i>How cut</i>	1	170.00	<i>+</i>	170.00
REAR TAILLAMP L/R	<i>LH covered</i>	2	498.00	<i>488</i>	996.00
Subtotal before discount					13,981.10
Percentage discount 5%					699.06
Sub-total 1					13,282.05
REAR BUMPER CLIPS - SET	<i>me</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER NUMBER PLATE	<i>Bent</i>	1	25.00	<i>✓</i>	25.00
REAR BUMPER NUMBER PLATE HOLDER	<i>Demol</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER RIVET - SET	<i>me</i>	1	100.00	<i>30</i>	100.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>me</i>	1	40.00	<i>20</i>	40.00
REAR LH TAILGATE INNER TRIM BOARD CLIPS - SET	<i>me</i>	1	50.00	<i>30</i>	50.00
REAR LH TAILGATE WINDSCREEN OUTER CHROME CLIPS - SET	<i>me</i>	1	80.00	<i>+</i>	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ABSOLUTE TECH PTE LTD
 64C PAGODA STREET
 SINGAPORE 059223

Contact : 91453949

TAX INVOICE

Repair Code : CLM17761
 Date in : 13/05/2023
 Vehicle Num. : SLU5536K
 Model : MINI COOPER S CLUBMAN AT LED NAV
 Chassis/Eng# : WMWLN720402G78713/F329H554B48A20A

REAR LH TAILGATE WINDSCREEN SEALANT	<i>M</i>	1	80.00	<i>50</i>	80.00
REAR RH TAILGATE INNER TRIM BOARD CLIPS - SET	<i>M</i>	1	50.00	<i>30</i>	50.00
REAR RH TAILGATE WINDSCREEN OUTER CHROME CLIPS - SET	<i>new</i>	1	80.00	<i>+</i>	80.00
REAR RH TAILGATE WINDSCREEN SEALANT	<i>not M</i>	1	80.00	<i>+</i>	80.00
Subtotal before discount					715.00
Percentage discount 0%					0.00
Sub-total 2					715.00
Parts-total					13,997.05

LABOUR

- To reset system after repair works
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

250
~~500.00~~
 ✓ 80.00
100 ~~280.00~~
60 100.00
2290 *800* 1,200.00
80 100.00
800 1,200.00
60 120.00
80 160.00

Labour Total 3,740.00
Parts & Labour Total 17,737.05

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey (before/after spray painting)
 • To display changed parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 This is a computer-generated document which requires no signature.
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

page 4

Achim Lij
n/s 16/05/23
07 Days
total: 10941.09
c/s: 8750 ✓