

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIS23005004/UP3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒ N/S	☐ O/S
☐	☐

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car (M.Cycle) / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRY SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Preli. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Fakran Afiq Bin Mazruddin
(94517789)

Accident Date : 04-May-23

Yamaha MT-03

Vehicle No : FBR8421Y (COE24072028)

Vehicle Model : ABS (MTN320-A)

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender <i>cu7</i>	<i>155</i> \$ 180.00 ✓
1	Front fork assy <i>cu7</i>	<i>820</i> \$ 1,050.00 ✓
1	Fork under bracket <i>3uf</i>	<i>285</i> \$ 450.00 ✓
1	Front rim <i>17</i>	\$ 550.00 X
1	Front rim shaft <i>17</i>	\$ 145.00 X
1	Front rim bearing <i>17</i>	\$ 120.00 X
1	Front brake disc <i>17</i>	\$ 285.00 X
1	Front signal (1 set) <i>115 scr</i>	<i>60</i> \$ 160.00 ✓
1	Handle-bar <i>3uf</i>	<i>290</i> \$ 355.00 ✓
1	Handle bar end <i>cu7</i>	<i>45</i> \$ 170.00 ✓
1	Hand grip <i>17</i>	\$ 125.00 X
1	Front lower cover <i>cu7</i>	\$ 280.00 ✓
1	Radiator inner cover <i>cu7</i>	\$ 185.00 ✓
1	Radiator cover <i>cu7</i>	\$ 230.00 ✓
1	Clutch lever <i>3uf</i>	<i>80</i> \$ 125.00 ✓
1	Gear pedal <i>3uf</i>	<i>115</i> \$ 165.00 ✓
1	Rider footrest (1 set) <i>115 cre</i>	<i>90</i> \$ 200.00 ✓
1	Rider footrest bracket (1 set) <i>17</i>	\$ 380.00 X
1	Pillion footret (1 set) <i>115 cu7</i>	<i>90</i> \$ 150.00 ✓
1	Pillion footrest bracket (1 set) <i>115 cu7</i>	<i>190</i> \$ 380.00 ✓
1	Engine cover <i>cu7</i>	<i>425</i> \$ 680.00 ✓
1	Side stand <i>2</i>	\$ 135.00 X
		\$ 6,500.00
	Less 10%	\$ 650.00
		\$ 5,850.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Fakran Afiq Bin Mazruddin
(94517789)

Accident Date : 04-May-23

Yamaha MT-03

Vehicle No : FBR8421Y (COE24072028)

Vehicle Model : ABS (MTN320-A)

Estimated Repair Costs

Special Net Items

1	Number plate	512	\$	38.00	10
2	Fork oils	11	\$	30.00	X
2	Fork oil seals	11	\$	56.00	X
1	Steering cone (1 set)	11	\$	120.00	60
1	Rear box	617	\$	580.00	400
1	Rear box bracket	11	\$	180.00	X
			\$	1,004.00	

<u>S/No.</u>	<u>Labour</u>				
1	To provide towing service (LOD) \$70.00		\$	-	
2	To check wiring and reset headlamp focusing		\$	80.00	X
3	To repair body frame		\$	420.00	X
4	To provide labour		\$	450.00	300
			\$	950.00	

Grand Total

\$ 7,804.00

Singapore Dollars: Seven Thousand Eight Hundred and Four only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3340
102
3006
470
300
3776
204
3520