



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23005005/Uny3q2 Date: 29/05/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKS 3886K	Veh. Inspected	SNF 3901H	
Policy No.	P10045651R05	Coverage (\$)	0.00	
Claim No.	C10022238/JY	Excess (\$)	0.00	
Assign From	LEONG ENG MING	Assign Date	16/05/2023	
2. Vehicle Particulars & Condition				
Make & Model	BYD E6 (ME-2) (A)	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	LC0CE4DC9N0064819	Colour	BLACK	
Odometer	85167 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	CHAO YANG	5 mm	
L/H Front Tyre	215/55 R17	CHAO YANG	5 mm	
R/H Rear Tyre	215/55 R17	CHAO YANG	5 mm	
L/H Rear Tyre	215/55 R17	CHAO YANG	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2023	Inspection Date	17/05/2023	
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		