

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: SMRT BUSES LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Document No.	: SQT23001485	Page	1
Registration No	: SMK7846T	Date	: 16. May 2023		
Chassis No	: JHMGK3850KS213685	Customer No.	: WZS001		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: LIM WEE LEE	Engine No	: L13B14100896		
Ins Policy No.	:	Date Time	: 16. May 2023 8:43:20 AM		
Date of Accident	: 10/5/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM WEE LEE OWNER INSURER: TOKIO MARINE ACC DATE: 10/05/2023 SURVEYED BY: DATE: REF NO: TP INSURER: SMRT TP VEH: SMB1637S						
67010-T5A-U00ZZ	PANEL COMPR.FR.DOOR	1	826.80	25	620.10	49.61	669.71
67324-T5A-003	TAPE SETR.FR.DOOR	1	35.90	25	26.92	2.15	29.07
72326-T5A-003	SEALFR.DOOR LOWER	1	21.10	25	15.82	1.27	17.09
72324-T5A-003	SUB SEALR.FR.DOOR	1	5.10	25	3.82	0.31	4.13
72410-TD4-003	MOLDING ASSYR.FR.DOOR	1	46.10	25	34.57	2.77	37.34
67510-T5A-306ZZ	PANEL COMP,R.RR.DOOR	1	814.80	25	611.10	48.89	659.99
67825-T5A-003	TAPER.RR.DOOR SASH	1	15.40	25	11.55	0.92	12.47
72825-T5A-013	SUB SEALR.RR.DOOR CENTER	1	47.00	25	35.25	2.82	38.07
72826-T5A-003	SEALRR.DOOR LOWER	1	3.90	25	2.92	0.23	3.15
72840-T5A-003	CHECKER COMPR.RR	1	40.60	25	30.45	2.44	32.89
67910-SWA-H11ZZ	HINGER.RR.DR.UPPER	1	37.80	25	28.35	2.27	30.62
67920-SWA-H11ZZ	HINGER.RR.DR.LOWER	1	37.80	25	28.35	2.27	30.62
04636-T5A-300ZZ	PANEL SETR.RR.OUTSIDE	1	610.70	25	458.02	36.64	494.66
04631-T5A-300ZZ	PANEL SETR.SIDE SILL	1	253.70	25	190.27	15.22	205.49
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	496.90	25	372.67	29.81	402.48
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	18.10	25	13.57	1.09	14.66
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	18.10	25	13.57	1.09	14.66
76208-T5A-J32	MIRROR ASSY,R.	1	542.20	25	406.65	32.53	439.18
76201-T5A-J31A2	SKULL CAP,R, ST	1	55.70	25	41.77	3.34	45.11

Printed on 16/5/2023 9:02:30 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: SMRT BUSES LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Document No.	: SQT23001485	Page	2
Registration No	: SMK7846T	Date	: 16. May 2023	Customer No.	: WZS001
Chassis No	: JHMGK3850KS213685	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L13B14100896
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Date Time	: 16. May 2023 8:43:20 AM	Surveyor Name	:
Owner's Name	: LIM WEE LEE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 10/5/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
33500-T5A-J02	TAILLIGHT ASSY,R.	1	258.40	25	193.80	15.50	209.30
Sum Item					3139.52	251.17	3,390.69
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	22.40	302.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	22.40	302.40
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	650.00		650.00	52.00	702.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00		650.00	52.00	702.00
BOJSE	BODY JOINT SEALANT FR DOOR	1	120.00		120.00	9.60	129.60
BOJSE	BODY JOINT SEALANT RR DOOR	1	120.00		120.00	9.60	129.60
BOBC	BODY UNDERSIDE COATING (N)	1	380.00		380.00	30.40	410.40
BKFE22K	STRAIGHTEN ALIGN RR R FENDER.	1	5200.00		5200.00	416.00	5616.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4160.00		4160.00	332.80	4492.80
Sum Labor					11940.00	955.20	12,895.20

Survey By				
Date & Time		Total Amount	15,079.52	1,206.37
Excess		Total (Inclusive of GST)		16,285.89
Status				
Signature				

Printed on 16/5/2023 9:02:30 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.