



# YEW HOK AUTO SERVICES

44 Chai Chee Street, # 10-124, Singapore 461044

H/P: 8285 7623

Email: yhlee@outlook.sg

Vehicle number: GBL6637L

Vehicle Made & Model: NISSAN NV 350

Qty	Nett Items		Amount \$
1	Front bumper	Dis/Toon	636.80 656.60 ✓
1	Front bumper fog lamp cover - LH	scr	158.70 ✓
1	Front bumper grille	Toon	155.10 ✓
1	Front bumper reinforcement	scr	495.50 ✓
1	Front bumper side retainer - LH	one	199.10 ✓
1	Front cab panel	Body	1367.80 1,485.00 ✓
1	Front corner panel - LH	n	587.00 X
1	Front grille	one	596.20 ✓
1	Front grille logo	11	86.60 X
1	Front headlamp - LH	one	516.10 638.60 ✓
1 set	Front windscreen moulding	n	120.60 ✓
1	Air con blower assy	one	1,055.90 ✓
1	Air con pipe	tw	189.60 ✓
1	Oil cooler	scr	870.70 X
1	Oil cooler air guide	scr	187.20 ✓
<b>Sub-total</b>			<b>7,482.40</b>
<b>Less 10%</b>			<b>748.24</b>
<b>Total Nett</b>			<b>6,734.16</b>

not allowed  
 del  
 n/m)  
 L/S \$5800  
 5 days.  
 18/5/23

Vehicle number: GBL6637L

Vehicle Made & Model: NISSAN NV 350

**Special Nett Items**

1 set	Front bumper clip	<i>ncc</i>	50.00	<i>30</i>
1 set	Front windscreen sealant	<i>nu</i>	80.00	<i>40</i>
1	R.O.V sticker	<i>nu</i>	45.00	<i>30</i>
			<b>Total Special Nett</b>	<b>175.00</b>

**Labour charges**

To remove, refix front windscreen	180.00	<i>120</i>
To remove, refix front interior trims to assist repair	<i>11</i> 120.00	<i>X</i>
To remove, refix front dashboard	350.00	<i>200</i>
To remove, refix A/C cooling system/refill A/C gas	250.00	<i>100</i>
To respray undercoating	100.00	<i>30</i>
To respray painting and etc	1,000.00	<i>800</i>
Panel beating, cut, weld remove & replacing above parts	1,000.00	<i>800</i>
<b>Total Labour</b>		<b>3,000.00</b>

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 9,909.16**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*P-5678.6*  
*102*  
*P-5110.74*  
*S.N-100*  
*L-2050*  

---

*7260.74*  
*202*  

---

*5808*