

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLG4140Z
 Accident Date : 13-May-2023

No. : 06833

Date : 16-May-2023

Our Ref : 023107 (III) / CHAN

PAGE : 1

SUN YAWEI
 85 YISHUN STREET 81
 #04-07
 Singapore 768447

Not Notified
L1 Rep &
Money After Paint
2 days

ESTIMATED COST OF REPAIR FOR AUDI A4 SLC6205D

- 1 pc Rear bumper fascia
- 1 pc Rear bumper lower spoiler
- 1 pc Rear bumper reinforcement
- 2 pcs Rear bumper parking sensor

	<i>Bumper</i> 2,007.65	✓
	<i>nd/wr</i> 261.04	✓
	869.84	✓
@ S\$209.53	419.06	✓
	3,557.59	
Less 10% :	355.76	
	3,201.83	

To putty and spray replaced parts

400.00 *22d*

To remove, cut-out damaged parts,
 panel beating, welding, align,
 refix and to renew above parts

500.00 *20d*

To rewire rear parking sensor wire

50.00 ✓

Total : S\$ 4,151.83

Singapore Dollars Four Thousand One Hundred and
 Fifty One and Cents Eighty Three Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: