

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. ER 819B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER PANEL (RH)	TO REPAIR SEE LABOUR	6,829.95	-
1	REAR FENDER ARCH PROTECTOR (RH)	DENTED/ DEFORMED	685.95	535.90
1	REAR FENDER ARCH PROTECTOR REAR RETAINER (RH)	CRACKED	250.75	195.90
1	REAR FENDER INNER SHIELD (RH)	DEFORMED/ CRACKED	327.55	255.90
1	REAR FENDER INNER SHIELD CLIPS (RH)	NECESSARY	109.44	85.50
1	REAR BUMPER ASSEMBLY	TORN/CRACKED	2,989.44	2,335.50
1	REAR BUMPER SIDE PARKING SENSOR (RH)	CRACKED/BROKEN	417.15	325.90
1	REAR BUMPER SIDE RETAINER (RH)	CRACKED	237.95	185.90
1	REAR AXLE WHEEL SHAFT (RH)	NOT NECESSARY	1,709.95	-
1	REAR RIGHT WINDSCREEN WITH MOULDING	NOT NECESSARY	2,989.95	-
	LESS 10% DISCOUNT		-1,654.81	-392.05
			14,893.27	3,528.45
	SPECIAL NETT ITEMS			
1	REAR WHEEL RIM (RH) (SN)	CHIPPED	4,500.00	2,500.00
			4,500.00	2,500.00
	LABOUR			
	TO PANEL BEAT RIGHT REAR FENDER PANEL AND REPLACE RIGHT REAR. INCLUSIVE OF THE REPAIR OF REAR FENDER PANEL (RH).		1,200.00	800.00
	TO REMOVE/INSTALL RIGHT REAR AXLE WHEEL SHAFT TO REPLACE.	NOT NECESSARY	250.00	-
	TO REMOVE/INSTALL RIGHT REAR BUMPER SIDE PARKING SENSOR TO.		100.00	50.00
	RUST PROOFING ON THE RIGHT REAR ACCIDENT PORTION.		80.00	40.00
	TO PUTTY AND RESPRAY RIGHT REAR FENDER PANEL, RIGHT REAR FENDER.		800.00	600.00
			2,430.00	1,490.00
	GRAND TOTAL		21,823.27	7,518.45

Report Ref No. CS3/INC22011506/Tvy3m4-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	6,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/INC22011506/Tvy3m4-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.