



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: RAJESWARY			Ref: CS3/INC22011506/Tvy3m4-1 Date: 19/06/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 7872J	Veh. Inspected	ER 819B
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1197045-002	Excess (\$)	0.00
	Assign From		Assign Date	05/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ G63 AMG	c.c	3982
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	W1N4632762X380408	Colour	BLACK
	Odometer	22796 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/40 R22	PIRELLI	6 mm
	L/H Front Tyre	295/40 R22	PIRELLI	6 mm
	R/H Rear Tyre	295/40 R22	PIRELLI	6 mm
	L/H Rear Tyre	295/40 R22	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2022	Inspection Date	18/11/2022
	Survey held at	RS GARAGE SERVICES PTE LTD BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	