

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TO	: ERGO	DATE	15/5/2023
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	T/P CLAIM
VEHICLE DETAILS			
VEHICLE NO	: SMG5055T	2018	Xiao Chan.
VEHICLE MODEL	: MERCEDES BENZ CLA180		
CHASSIS NO	: WDD1173422N691421		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR BUMPER <i>Distal d</i>	1	\$ 1,338.00	\$ 1,338.00	✓
2	RAER BUMPER SIDE HOLDER <i>Replaced</i>	1	\$ 98.00	\$ 98.00	✓
3	REAR BUMPER BRACKET <i>Replaced</i>	1	\$ 72.00	\$ 72.00	✓
4	REAR BUMPER AIR VENT <i>Replaced</i>	1	\$ 65.00	\$ 65.00	✓
5	REAR BUMPER LOWER GARNISH <i>Distal d</i>	1	\$ 425.00	\$ 425.00	✓
6	REAR BUMPER LOWER GARNISH EXHAUST CHROME <i>But</i>	1	\$ 289.00	\$ 289.00	✓
7	REAR BUMPER LOWER GARNISH EXHAUST CHROME BRACKET <i>Replaced</i>	1	\$ 85.00	\$ 85.00	✓
8	REAR BUMPER REINFORCEMENT <i>New</i>	1	\$ 645.00	\$ 645.00	+
9	REAR BUMPER BLIND SPOT SENSOR <i>Replaced</i>	1	\$ 1,095.00	\$ 1,095.00	✓
10	REVERSE SENSOR <i>1 piece damaged</i>	2	\$ 268.00	\$ 536.00	268. ✓
11	REVERSE SENSOR HOLDER <i>New</i>	4	\$ 25.00	\$ 100.00	✓
12	REAR END PANEL <i>Distal d</i>	1	\$ 1,012.00	\$ 1,012.00	✓
13	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 184.00	\$ 184.00	+
14	TAILLAMP <i>Replaced</i>	1	\$ 832.00	\$ 832.00	✓
15	TAILLAMP LOWER BRACKET <i>Replaced</i>	1	\$ 45.00	\$ 45.00	✓
16	TAILLAMP PANEL <i>Distal d</i>	1	\$ 214.00	\$ 214.00	✓
17	BOOTLID <i>Replaced</i>	1	\$ 1,875.00	\$ 1,875.00	+
18	BOOTLID WEATHERSTRIPE <i>New</i>	1	\$ 288.00	\$ 288.00	+
19	MERCEDES BENZ LOGO <i>3 piece</i>	1	\$ 78.00	\$ 78.00	✓
20	CLA180 WORDING	1	\$ 86.00	\$ 86.00	✓
21	REAR FENDER <i>Distal d</i>	1	\$ 2,201.00	\$ 2,201.00	✓
22	REAR FENDER INNER SHIELD <i>3 piece</i>	1	\$ 198.00	\$ 198.00	✓
23	REAR FENDER INNER TRIM BOARD	1	\$ 388.00	\$ 388.00	✓
24	REAR FENDER AIR VENT <i>Replaced</i>	1	\$ 89.00	\$ 89.00	✓
25	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 195.00	\$ 195.00	✓
26	REAR WHEEL RIM <i>New</i>	1	\$ 1,280.00	\$ 1,280.00	+

*Rear Bumper Blind Spot ? 185 ✓
Module Holder
Replaced*

9338

8404.20

TOTAL PRICE: \$ 13,464.00
LESS 10% \$ 1,346.40
SUB TOTAL PRICE: \$ 12,117.60

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT BUMPER CLIPS <i>Replaced</i>	1 SET	\$ 50.00	\$ 50.00	✓
2	REAR END PANEL TOP GARNISH CLIPS <i>Replaced</i>	1 SET	\$ 20.00	\$ 20.00	+

3	REAR END PANEL SEALANT <i>3pc</i>	1	\$	60.00	✓
4	TAILLAMP PANEL SEALANT	1	\$	40.00	✓
5	REAR FENDER INNER SHIELD CLIPS <i>3pc</i>	1 SET	\$	30.00	✓
6	REAR FENDER INNER TRIM BOARD CLIPS	1 SET	\$	30.00	✓
7	REAR FENDER SEALANT <i>3pc</i>	1	\$	60.00	✓
8	REAR WINDSCREEN SEALANT	1	\$	60.00	✓
9	REAR TYRE <i>the new</i>	1	\$	300.00	✓

TOTAL :

330

LABOUR

	JOB	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,800.00	1400
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	1200
3	WIRING CHECK	\$ 100.00	30
4	TO SPRAY TUFF COAT	\$ 150.00	80
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50
6	TO REMOVE REAR CAMERA	\$ 100.00	X
7	TO REMOVE UPHOLSTERY	\$ 150.00	80
8	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	X
9	TO REMOVE REAR WINDSCREEN	\$ 180.00	120
10	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	X
11	TO PERFORM DIAGNOSTIC TEST	\$ 250.00	180
12	TO CALIBRATE BLIND SPOT SENSOR	\$ 380.00	300
13	TOWING FEES (KING ROLLER)	\$ 120.00	✓

TOTAL: \$ 5,230.00

3760

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,767.60

TOTAL LABOUR COST: \$ 5,230.00

TOTAL REPAIR COST: \$ 17,997.60

total: 12494.20

4/5: 101C.

08 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: