



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3473E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-----------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT LH DOOR | BENT | 1,407.80 | 1,126.90 |
| 1 | FRONT LH DOOR WEATHERSTRIP | SERVICEABLE | 250.70 | - |
| 1 | LH SIDE MIRROR | DENTED/ CRACKED | 1,399.60 | 1,023.00 |
| 1 | FRONT LH DOOR OUTER HANDLE | SERVICEABLE | 423.20 | - |
| | LESS 25% DISCOUNT | | - | -537.47 |
| | | | 3,481.30 | 1,612.43 |
| | <u>LABOUR</u> | | | |
| | REMOVE & FIX BACK FRONT LH DOOR | | 1,000.00 | 500.00 |
| | REPAIR REAR LH DOOR & FENDER. | | | |
| | REMOVE & FIX BACK FRT LH DOOR MECHANISM. | | 100.00 | 60.00 |
| | REMOVE & FIX BACK SIDE MIRROR. | NOT NECESSARY | 100.00 | - |
| | SPRAY PAINTING. | | 1,000.00 | 800.00 |
| | | | 2,200.00 | 1,360.00 |
| | GRAND TOTAL | | 5,681.30 | 2,972.43 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 2,350.00 |

Report Ref No. CS/LIP23005021/Kny3m4

MARKET VALUE: \$62,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,882.00=NETT VALUE: \$41,118.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.