

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 22 May 2023

Preliminary Advice

Vehicle No	: SKW8221A	Accident Date	: 13/05/2023
Make	: TOYOTA CAMRY	Policy No.	: MPC22P00240900
Assignment Date	: 16/05/2023	Excess	: S\$750.00
Date of Inspection	: 17/05/2023	Est. Duration of Repair	: 5
Inspection At	: CONVERGENCE AUTOMOTIVE PTE LTD (HQ) 39 WOODLANDS CLOSE, MEGA@WOODLANDS #01-24 SINGAPORE 737856		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,301.00
Revised Amount	:S\$	5,360.50
Check Items (Estimated)	:S\$	1,188.00
Total	:S\$	6,548.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	33,867.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,133.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :the vehicle repair on part by parts basis,due to no second hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.