

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBH888P

NOT Notarized
11 Sep &
Heavy After Paint
6 days

No.	Qty	List Items
1	1	Rear deck end panel
2	1	RH taillamp bracket
3	1	RH taillamp
4	1	Rear number plate bracket
5	1	Rear number plate lamp
6	1	Rear lower spare tyre carrier chain
7	1	Rear lower exhaust silence/ pipe

\$	<i>By</i>	1,535.70	—
\$	<i>By</i>	157.80	—
\$	<i>cm</i>	280.12	—
\$		176.43	7
\$	<i>in</i>	122.60	X
\$		399.80	7
\$	<i>n</i>	1,754.60	X
\$		4,427.05	
Less 25%	\$	1,106.76	
Total :	\$	3,320.29	

		Special Nett Items
8	2	Rear box tailgate
9	2	Rear box tailgate lower hinge
10	1	Rear box RH tailgate lock bar

<i>By</i>	\$	3,600.00	✓
	\$	<i>n</i> 500.00	X
	\$	<i>By</i> 1,300.00	✓
Total :	\$	5,400.00	

		Labour
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.
2		To putty and spray Spray Paintings charges.
3		To remove, refit both rear box tailgates.
4		To check wirings and lightings.
5		To remove, refit rear exhaust pipe.
6		To supply and apply anti rust treatment

\$	1,000.00	<i>800</i>
\$	800.00	<i>250</i>
\$	200.00	<i>130</i>
\$	40.00	<i>20</i>
\$	<i>nn</i> 80.00	X
\$	60.00	<i>30</i>
Total :	\$	2,180.00

Total Parts and Labour : \$ 10,900.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: