

AGL 23 005030 1Ky

Kenneth

1074

Des. of Damages : Frit / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBH888P

Not Notched
11 Sep & 520ch
McRury After Pain
6 days

No.	Qty	List Items
1	1	Rear deck end panel
2	1	RH taillamp bracket
3	1	RH taillamp
4	1	Rear number plate bracket
5	1	Rear number plate lamp
6	1	Rear lower spare tyre carrier chain
7	1	Rear lower exhaust silence/ pipe

685.10

\$	R	1,535.70	—
\$	R	157.80	—
\$	CM	280.12	—
\$	R	176.43	✓
\$	R	122.60	X
\$	BH7A	399.80	✓
\$	R	1,754.60	X
\$		4,427.05	
Less 25%	\$	1,106.76	
Total :	\$	3,320.29	

Special Nett Items

8	2	Rear box tailgate
9	2	Rear box tailgate lower hinge
10	1	Rear box RH tailgate lock bar

\$	R	3,600.00	✓ 3200
\$	R	500.00	X
\$	R	1,300.00	✓ 800
Total :	\$	5,400.00	

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To remove, refit both rear box tailgates.
4	To check wirings and lightings.
5	To remove, refit rear exhaust pipe.
6	To supply and apply anti rust treatment

\$		1,000.00	800
\$		800.00	250
\$		200.00	150
\$		40.00	20
\$	R	80.00	X
\$		60.00	30
Total :	\$	2,180.00	

Total Parts and Labour : \$ 10,900.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: