

# Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

Tel: 6468-2200 fax: 6278-5535

GST:200000606-K RCB NO: 200000606-K

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL:

ATTN: MOTOR CLAIM DEPARTMENT

Your Ref No: SJA1802Y

Claim Type: Third Party

Accident Date: 04/05/2023

TP Veh Reg No: SJE7229S

**LABOUR \$400 SPRAY PAINT \$450**

Estimate No: WQT0000244

Date: 11/05/2023

Policy No:

Veh Reg No: SJA1802Y

Make/Model: SSANGYONG TIVOLI

XLV 1.6G (A) E6

Chassis No: KPT36A1VSGP097496

Engine No: 17391002050882

Reg.Date: 17/02/2017

## Estimate Repair Cost to Vehicle No :

NO.	Description	Quant	List Price	Amount
			\$\$	\$\$
1	FRONT BUMPER <i>cut</i>	1pc	985.605	985.605
2	FRONT BUMPER RETAINER <i>? Xan</i>	LH 1pc	68.94	68.94 X
3	FRONT HEADLAMP <i>X an</i>	LH 1pc	1957.5	1957.5 X
4	FRONT FENDER <i>bt</i>	LH 1pc	794.76	794.76
5	FRONT FENDER WHEEL ARCH MOULDING <i>sc</i>	LH 1pc	135.63	135.63
6	FRONT FENDER UNDER-DUST COVER <i>Xm</i>	LH 1pc	135.63	135.63 X
7	FRONT FOGLAMP GARNISH <i>X an</i>	LH 1pc	142.5	142.5 X
8	FRONT DOOR <i>bt</i>	LH 1pc	1800.00	1800.00
9	FRONT DOOR UPPER HINGE <i>X an</i>	LH 1pc	55.00	55.00 X
10	FRONT DOOR LOWER HINGE <i>? Xan</i>	LH 1pc	55.00	55.00 X
11	REAR DOOR <i>bt repair</i>	LH 1pc	1800.00	1800.00 XR
12	REAR FENDER WHEEL ARCH MOULDING <i>Xan</i>	LH 1pc	135.63	135.63 X
13	SIDE SKIRT <i>sc</i>	LH 1pc	283.365	283.365
14	REAR BUMPER UPPER <i>X an</i>	1pc	912.75	912.75 X
15	FRT STABILIZER BAR ASSY <i>? Xan</i>	LH 1pc	184.20	184.20 X
16	FRT STABILIZER BAR LINK <i>? Xan</i>	LH 1pc	46.10	46.10 X
17	FRT SUSPENSION LWR ARM ASSY RH <i>? Xan</i>	LH 1pc	173.26	173.26 X
18	FRT SUSPENSION DAMPER RH <i>? Xan</i>	LH 1pc	202.38	202.38 X
19	GEAR & OBJ LINKAGE ASSY <i>? Xan</i>	LH 1pc	781.76	781.76 X

3999.35	TOTAL	10650.01
10%	LESS 10%	1065.001
3599.41	TOTAL	9585.01

<u>SPECIAL NETTS</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	RIM <i>SLA</i>	<i>2 pc</i>	<del>800.00</del> <i>400</i>	1600.00
2	SIDE SKIRT CLIPS <i>m</i>	1pc	40.00 ✓	40.00
3	FRONT BUMPER CLIPS <i>m</i>	1pc	40.00 ✓	40.00
			<i>480</i>	TOTAL
				1680.00

<u>LABOUR CHARGE</u>				
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.			\$ <i>1600</i> <del>2,400.00</del>
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	<i>3840</i>		\$ <i>1800</i> <del>2,700.00</del>
3	TO CARRY OUT DIAGNOSTIC TEST			\$ <i>200</i> <del>400.00</del>
4	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTINGS & RESET HEADLAMPY FOCUSING			\$ <i>40</i> <del>120.00</del>
5	REMOVE FRONT UNDERCARRIAGE PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING REPLACING AFFECTED UNDERCARRIAGE PARTS AND PERFORM COMPUTERISED ALIGNMENT AND STEERING ALIGNMENT (STEERING ANGLE ZEROING)			\$ <i>200</i> <del>480.00</del>
		TOTAL		\$ 6,100.00
		TOTAL PARTS		\$ 11,265.01
		GRAND TOTAL		\$ 17,365.01

3599.41  
 480.00  
 3840.00  


---

 7919.41  
 20%  
 6335.53  


---

 48 - \$6,300 / 8 days

**LKK Auto Consultants** hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
  
 Acknowledged by Repairer  
 Signature:  
 Date:

*Paul*  
*Hp 9000068*  
*8 days*  
*L/S*  
*17/05/23 @ 1230*  
*Resy after repair*