




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23005038/Rvp3m4 Date: 31/05/2023 Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 4728Y	Veh. Inspected	FBA 4528P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/23/2054	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	17/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c	399
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	JH2NC39925M100463	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/60ZR17	MICHELIN	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60ZR19	MICHELIN	3 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 			
5. General Information				
	Accident Date	21/04/2023	Inspect Date / Time	19/05/2023 (05:23 PM)
	Survey held at	ROCKETRENTAL PTE LTD 5 SOON LEE STREET, #01-44, PIONEER POINT, SINGAPORE 627607		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500-\$1,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

Report Ref No. CS3/SMR23005038/Rvp3m4

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.