



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS3/HSB23005042/Rnp3m4

10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2 SINGAPORE
018983

Date: 26/05/2023

ATTN: LOW GARNET

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 5045M	Veh. Inspected	AT 22U
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04M3D	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	17/05/2023

2. Vehicle Particulars & Condition


Make & Model	YAMAHA FINO 115	c.c	114
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	4D0281411	Colour	MULTI
Odometer	02734 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/90-14	SHINKO	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/80-14	SHINKO	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.



5. General Information

Accident Date	28/04/2023	Inspect Date / Time	17/05/2023 (02:21 PM)
Survey held at	RWAVE PTE LTD 50 BUKIT BATOK STREET 23 #02-25 MIDVIEW BUILDING SINGAPORE 659578		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

Report Ref No. CS3/HSB23005042/Rnp3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.