



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNA2438L

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711  
63476100

### Vehicle & Document Information

WIP No 10007  
Reg No/Reg Date SNA2438L / 29/07/2022  
Date In/Mileage / 0  
Chassis No W1N2477842J4102169  
Engine No 28291480845377  
Make/Model MB/GLA 180  
Colour/Trim 027 787 Mountain Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	17/05/2023/ 10:31	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

### Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 7220079532 // 15-5-2023

DRIVE IN/TP VEH NUMBER : 16-5-2023 // SLP9640S - III

DATE IN/DATE SURVEY:

DIRECT SETTLEMENT BY:

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray LH/REAR DOOR

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT

S BPNSUB

LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)

WHEEL BALANCE AND INSTALL NEW VALVE HEAD

M LH/REAR DOOR COVER STRIP

1.00 219.14 00.00

219.14

M LH/REAR FENDER COVER, BUMPER AREA

1.00 131.00 00.00

131.00

M LH/REAR DISK WHEEL

1.00 779.44 00.00

779.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature & accepted by

Date:

Go Chee Han

DID : 6771 4710

Email : cheehan@cycleandcarriage.com

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop, Singapore 128378

Tel: 6298 1818

Fax: 6779 5383

www.mercedes-benz.com.sg

Nett 4,509.58  
8% GST on 4509.58 360.77

Total Payable 4,870.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG