



Section A - Accident Details

Registration Number	SHD6180H
Case Reference Number	TAX/03/23/2071
Registration Date	3/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LOW SWEE EE
Type of Accident	Others
Accident Date and Time	29/Mar/2023 5:00 PM
Accident Reported Date and Time	30/Mar/2023 12:26 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118085
Special Instruction to ARC, if any	LEFT FRONT DOOR DAMAGED
Prepared Date and Time	3/Apr/2023 3:11 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$918.00	\$380.00
Total Spare Part Cost	\$6,062.46	\$1,521.60
Total Other Cost	\$648.44	(\$251.60)
TOTAL COST	\$8,473.90	\$2,050.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Irfan (LKK) / INCOME
ARC / Surveyor Sign Off Date	11/04/2023 2:53 PM	11/04/2023 12:59 PM
Signature		
Remarks	INITIAL = 6 DAYS WITH SUPPLEMENTARY = 0 DAY TOTAL = 6 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Irfan (LKK) / HP : 90097659 & Email : irfan@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0006	Invoice Number	
Quotation Date	03.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$100.00
TO RESPRAY DOOR HANDLE	\$180.00	\$0.00
TO RESPRAY DOOR HANDLE	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$918.00	\$380.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$540.04)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
TO REPLACE SUNDRY PARTS	\$100.00	\$30.00
Total Other Costs	\$648.44	(\$251.60)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	0.00	\$1,407.80	0.00	\$0.00	Replace	Check
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6872012151	HINGE ASSY, FRONT DOOR , UPPER LH	0.00	\$105.50	0.00	\$0.00	Replace	Check
		6874012120	HINGE ASSY, FRONT DOOR , LOWER LH	0.00	\$120.00	0.00	\$0.00	Replace	Check
		6980221010	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$257.80	0.00	\$0.00	Replace	Check
		8572047140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Check
		6786247050	WEATHERSTRIP, FRONT DOOR LH	0.00	\$250.70	0.00	\$0.00	Replace	Check
		6904047100	LOCK ASSY, FRONT DOOR LH	0.00	\$607.90	0.00	\$0.00	Replace	Check
		6941020110	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Check

X
√
X
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2023

User ID : PohSuan

		69210470 51A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$423.20	25.00	\$317.40	Replace	Replace	√
		87940474 40	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,454.40	0.00	\$0.00	Replace	Check	X
		87945470 60A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$88.35	Replace	Replace	√
Total					\$6,043.70		\$465.75			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	Replace
Total					1,407.80		1,055.85		

	1,521.60	
+	400.00	
+	<u>668.44</u>	L/S \$2,050/-
	2,590.04	
	<u>-20%</u>	
	2,072.03	