

L APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Foo Sake Liang
C/o: Top Max Auto Body Shop
Blk 3007 Ubi Road 1
#01-410 Singapore 408701

Date : 19 December 2022
Our ref : TM/12/2201/TP

Accident Date : 5 December 2022
Inspection Date : 12 December 2022
Repairer Name : Top Max Auto Body Shop
Blk 3007 Ubi Road 1
#01-410 Singapore 408701

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SFJ 719 L
Make / Model : Renault Scenic
Chassis No : VF1RFA00061136884
Engine No : K9KF649D056992

Year / Capacity : 2018 / 1461 cc
Colour : Blue
Mileage : 29627

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside :	Continental	195/55 R20	5 mm	Sport
Front Offside :	Continental	195/55 R20	5 mm	Sport
Rear Nearside :	Continental	195/55 R20	5 mm	Sport
Rear Offside :	Continental	195/55 R20	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 72 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No.: SFJ 719 L

Our Ref No.:

TM/12/2201/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen inner seal <i>new</i>	Necessary	\$ 85.00	\$ 85.00 <i>+</i>
1	Rear tailgate <i>Reps</i>	Damage	\$ 2,850.00	\$ 2,850.00 <i>+</i>
1	Rear tailgate logo	Necessary	\$ 85.00	\$ 85.00 <i>✓</i>
1	Rear tailgate rubber <i>new</i>	Necessary	\$ 246.00	\$ 246.00 <i>+</i>
1	Rear tailgate "RENAULT" emblem	Necessary	\$ 68.00	\$ 68.00 <i>✓</i>
1	Rear tailgate "SCENIC" emblem	Necessary	\$ 85.00	\$ 85.00 <i>✓</i>
1	Rear end panel <i>Reps</i>	Intact	\$ 865.00	
1	Rear bumper	Damage	\$ 1,855.00	\$ 1,855.00 <i>✓</i>
2	Rear bumper lower side undercovers	Damage	\$ 310.00	\$ 310.00 <i>✓</i>
1	Rear bumper lower diffuser	Damage	\$ 785.00	\$ 785.00 <i>✓</i>
2	Rear bumper reflectors	Damage	\$ 236.00	\$ 236.00 <i>✓</i>
1	Rear bumper reinforcement	Damage	\$ 685.00	\$ 685.00 <i>✓</i>
1	Rear bumper inner garnish	Damage	\$ 322.00	\$ 322.00 <i>✓</i>
2	Rear bumper side retainers <i>new</i>	Necessary	\$ 130.00	\$ 130.00 <i>+</i>
1	Rear bumper lower moulding	Damage	\$ 485.00	\$ 485.00 <i>✓</i>
4	Rear bumper PDC sensors <i>2 pieces dnd</i>	Damage	\$ 1,260.00	\$ 1,260.00 <i>630</i>
1	Rear exhaust heat shield	Necessary	\$ 185.00	\$ 185.00 <i>✓</i>
			\$ 10,537.00	\$ 9,672.00
			<i>Less 20%</i> \$ 2,107.40	\$ 1,934.40
Total Cost - List Items			\$ 8,429.60	\$ 7,737.60

SPECIAL NETT ITEMS

1	Rear windscreen sealant <i>new</i>	Necessary	\$ 80.00	\$ 50.00 <i>+</i>
1	Rear bumper clip (1 set)	Necessary	\$ 80.00	\$ 80.00 <i>30</i>
Total Cost - Special Nett items			\$ 160.00	\$ 130.00

Total cost of parts

\$ 8,589.60 \$ 7,867.60

Vehicle Registration No.: SFJ 719 L

Our Ref No.:

TM/12/2201/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 8,589.60	\$ 7,867.60
<u>LABOUR</u>			
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 ³⁰
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 120.00	\$ 80.00 ⁴⁰
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 120.00 ⁵⁰
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 800.00	\$ 500.00 ⁴⁰⁰
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 850.00	\$ 660.00 ⁵⁰⁰
GRAND TOTAL		\$ 10,559.60	\$ 9,277.60

total - 5634.80

n/s: 4.51k

64 days

Vehicle Registration No.: SFJ 719 L

Our Ref No.:

TM/12/2201/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser