

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3S6620Y

at Workshop m/s: BHM

of _____

Insured: SHB1700B

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 18k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

846A

Vehicle: IN / OUT

Date: _____ Person Contacted: L7AS 7047

Veh No: F3S6620Y Yr Regn: 25/06/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda CRF 300L c.c 286

Colour: Red A/C: Insured / Std / NI / NA

Sp.Reading: 10385 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MLHND1680M*5001619

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80-100-21

R: 120-80-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 12C

Front: 8 Rear: 8

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 29/04/23 D.O.I. 19/05/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	new h.k. 22k have video of folder
	NETT \$ 10953

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____ Date/Time, File Return to?
 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	846A
Vehicle Details	
Vehicle No.:	FBS6620Y
Vehicle to be Exported:	No
Intended Deregistration Date:	19 May 2023
Vehicle Make:	HONDA
Vehicle Model:	CRF300L MANUAL
Primary Colour:	Red
Manufacturing Year:	2021
Engine No.:	ND16E1001619
Chassis No.:	MLHND1680M5001619
Maximum Power Output:	-
Open Market Value:	\$6,159.00
Original Registration Date:	25 Jun 2021
First Registration Date:	25 Jun 2021
Transfer Count:	1
Actual ARF Paid:	\$1,330.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$8,703.00
COE Rebate Amount:	\$7,047.00
Total Rebate Amount:	\$7,047.00

The information contained herein is correct as at 19 May 2023

OK

Advertisement

Motorcycles > Motorcycles for Sale > Class 2A



[Electronics](#)
[Fashion](#)
[Luxury](#)
[Services](#)
[Cars](#)
[Property](#)
[All Categories](#)

Search for anything

All of Singapore

S\$18,000

No

Used

Meetup

Waterfront Isle

Description

S\$ 1800

Posted	Make	Type
2 days ago	Honda	Enduro

2021 CRF300L for sale
 regular engine oil and filter changes
 New clutch plate
 Well taken care of with no rust
 Zeta levers and footpegs
 14 45 gearing for better pick up and acceleration
 upgraded front to brembro brakes and both front and rear is hel steel braided lines

read more

Search for anything

All of Singapore

Advertisement

Motorcycles > Motorcycles for Sale > Class 2A



PROTECTION

Honda crf250 rally

\$S\$19,000

Used

Meetup

Sembawang MRT Station (NS11)

@c 5.0

Description

Bumped

Make

Type

53 minutes ago

Honda

Scrambler

Honda crf 250 rally comes with full front and rear ohlins 2018 September selling for \$19000 Low mileage Whatsapp 98516255 for viewing

Meet-up

Sembawang MRT Station (NS11)



QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBS6620Y
MAKE/MODEL : HON / CRF300L MANUAL

*not allowed
all
repair
19/5/23
P/P/S
4 days
the she after up*

NO. : 43549

DATE : 17/05/2023
CLAIM NO. : 12188
POLICY NO. : PNMC2022-00002626
FROM : RAYMOND

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	<i>cu7</i> 66.00
2	AXLE WHEEL REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$114.00	<i>11</i> 114.00 X
3	BAR HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$236.00	<i>Surf</i> 236.00
4	BEARING STEERING CONE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	<i>ner</i> 48.00
5	BRACKET UNDER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$612.00	<i>Surf</i> 612.00
6	CABLE THROTTLE A - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	<i>cu7</i> 48.00
7	CABLE THROTTLE B - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	<i>cu7</i> 48.00
8	COVER SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$236.00	<i>cu7</i> 236.00
9	COWLING FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$306.00	<i>De</i> 306.00

*43549 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	CROWN HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$342.00	<i>CU7</i> 342.00 ✓
11	FOOTREST FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$154.00	<i>CU7</i> 154.00 ✓
12	FORK FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,288.00	<i>SC</i> 3,288.00 X
13	FORK FRONT RH - (REPORTED BY MECHANIC)	<i>photo?</i> REPLACE	1.00	\$3,288.00	<i>Drye</i> 3,288.00 ✓
14	FORK PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$131.00	<i>DIS</i> 131.00 ✓
15	GRIP HANDLE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	<i>ner</i> 24.00 ✓
16	GRIP HANDLE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$72.00	<i>CU7</i> 72.00 ✓
17	GUARD HANDLE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	<i>17</i> 233.00 X
18	GUARD HANDLE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	<i>CU7</i> 233.00 ✓
19	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$86.00	<i>500</i> 1,376.00
20	LAMP SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$342.00	<i>CU7</i> 342.00 ✓
21	LAMP SIGNAL REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$342.00	<i>CU7</i> 342.00 ✓
22	LEVER BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	<i>SCR</i> 32.00 ✓
23	MIRROR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	<i>CU7</i> 107.00 ✓
24	MIRROR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	<i>320</i> 107.00 ✓

*43549 *




S/N	Description	Action	Qty	Unit Price	Amount
25	MUDGUARD FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$330.00	Dis 330.00
26	MUFFLER COMP. - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,129.00	CU7 1,129.00
27	PACKING MUFFLER P/N: 49139 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	CU7 32.00
28	PEDAL BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$114.00	CU7 114.00
29	PROTECTOR EXHAUST - (REPORTED BY MECHANIC)	REPLACE	1.00	\$232.00	CU7 232.00
30	PROTECTOR EXHAUST CAP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	CU7 84.00
31	RIM FRONT ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,364.00	Try Repair 1,364.00 ?
32	RIVET - (REPORTED BY MECHANIC)	REPLACE	3.00	\$15.00	ner 45.00
33	SHROUD RH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	? 48.00
34	STAY METER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$306.00	But 306.00
35	STICKER 300L - (REPORTED BY MECHANIC)	REPLACE	1.00	\$189.00	ner 189.00
36	STICKER COVER SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$189.00	ner 189.00
37	STICKER FRONT COWLING - (REPORTED BY MECHANIC)	REPLACE	1.00	\$143.00	ner 143.00
38	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	ner 19.00 ¹⁰
39	TYRE 90/90-21 (SHINKO) 705 P/N: 67842 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$120.00	su 120.00 X

SUB TOTAL
GST @ 8 %

\$16,129.00
\$1,290.32

*43549 *



S/N	Description	Action	Qty	Unit Price	Amount
GRAND TOTAL (SGD)					\$17,419.32

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*43549 *

bizSAFE₃

