Tokio Marine Insurance Singapore Ltd.

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the Tokio Marine Group



Our ref: M2302820 Your ref: 59122MID

Date: 10 July 2023

WITHOUT PREJUDICE BY EMAIL ONLY

THE MINISTRY OF DEFENCE 303 GOMBAK DRIVE MINDEF BUILDING SINGAPORE 669645

Dear Sir

RE: RECOVERY ACTION IN RESPECT OF ACCIDENT INVOLVING GBF1478T & 59122MID ON 03/05/2023

Vehicle No. GBF1478T that was damaged in the above accident was insured with us under our Policy No. **MP003366.**

We have settled the cost of repairs to our insured vehicle. Please be advised that Clause 4 of the Treasury Collision Agreement (TCA) is applicable.

Our claim is set out hereunder:

Cost of repairs : \$ 11,826.00 (w/GST)

X 50%

Total : \$ 5,913.00

As such, we look to you to reimburse us the sum of \$5,913.00 within 14 days of receipt of this letter.

Copies of the following documents are enclosed in support of our claim:

- 1. GIA form of our insured
- 2. Survey report with photographs
- 3. Final invoice from repairer
- 4. Satisfaction cum discharge voucher executed by insured.

Kindly acknowledge receipt of these documents.

Yours faithfully,

For Tokio Marine Insurance Singapore Ltd.

Tan Wancong

Motor Claims Department

DID 6592 6414

Email: tanwancong@tokiomarine.com.sg

Encl.



SB0E23540001 / Ban Choon Motor Works ENTRY DATE & TIME: 04/05/2023 12:46 (SGT) SUBMITTED BY: Ng Tian Chuan VERSION: 1 (04/05/2023 12:46 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident**

Additional Location Information

Country/State of Loss

04/05/2023 12:46 (SGT)

Actual Driver

03/05/2023 14:30 (SGT)

70 Jurong Island Hwy, Singapore 627880 JURONG ISLAND (LAMP POST 71)

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBF1478T

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address Mobile Phone No

Alternative Phone No

KJM CURRY HOUSE & RESTAURANT PTE LTD

2XXXXX908N

kjmtkavi720@gmail.com (Phone) +65-83000980

VEHICLE PARTICULARS

Manufacturer

Model

CC

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

Toyota

Dyna

Employment

Yes

Commercial vehicle

Manual 2982

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Tokio Marine Insurance Singapore Ltd

MP003366

DRIVER

Name of Driver Passport No/FIN RAMADOSS BALAKRISHNAN GXXXX428N

Date Of Driving Pass 26/12/2012 Driving experience 10 YEARS AND 5 MONTHS Gender Mobile Number (Phone) +65-83000980 Alt. Phone Number Email Address Address Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions DIZZLING Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name Jurong West Neighbourhood Police Centre Police Station Phone No. (Phone) +65-18002689999 Alt. Police Station Phone No. (Fax) +65-62672438 Police Station Address 700 Corporation Road Singapore 649818 Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO POLICE REPORT NO. T/20230504/2042 ATTACHED. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number

59122MID

Vehicle Manufacturer Vehicle Model

Vehicle Colour	
Vehicle Category	Government
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	1


SKETCH PLAN

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: - NRIC/FIN No.:
DECLARATION I/We declare the following ha	rticulars are true in every respect.	
	outen	ched
	7 2023050	4 2042
	Pepat No	
	Refer to Police	٠
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT	


GIARAIC Sterch Plansform_VS


















Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 1 of 3 Report No. T/20230504/2042

REPORT	OF A	ATRAFFIC	ACCIDENT

Date/Tim 04/05/20			Vide Report No.:				Station Diary No.: 131	
Informar	nt's Parti	culars						
Name of Informant: RAMADOSS BALAKRISHNAN		Addr	ess:					
		1						
ID Type / FIN NO /					e: 830	000980		
Nationali INDIAN	ty:		Ema	1:			(
Sex: Male	Age: 39	Date of Birth: 07/04/1984	Type	of Informan	t			
Race: Indian								
Occupation CHEF	on:		Driving Licence Information: Class: 2B,3,4 Date of			of Expiry:		
General li	nformati	on of the Accident						
Type of Accident:		Non-Injury Government Vehicle	le	Drink Drive: No	Date/Time of Accident: 03/05/2023 14:3	0	Type of Location: Bend	
Location:								
JURONG	ISLAND	HIGHWAY						
Lamp Po	st Numbe	er: 71	6					
Weather: Cloudy			Road	d Surface:				
Traffic Flo			ic Control: Controlled			ffic Volume: Traffic		
Type of Collision: Between Moving Vehicles - Head To R			Rear				one conveyed by bulance:	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
59122MID	Lorry				Slightly Damaged	0
GBF1478T	Lorry	TOYOTA	DYNA 3.0 MANUAL	White	Seriously Damaged	

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/22/305/04/2042

2 of 3

Report No. T/20230504/2042

Police Station Of Origin: Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999 CONTINUATION OF REPORT

Driver					
Name	RAMADOSS BALAKRISHNAN		ID No		428N
Related Vehicle	GBF1478T (Lorry)		Conta	ct No.	83000980
Hospital/Clinic	NIL		Class Drivin Licend Expiry	g	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave NIL	Degree of	f Injury	NIL	

Brief Details.

I am working as a supervisor and driver under KJM CURRY HOUSE & RESTAURANT PTE LTD.

On 04/05/2023 at about 1430hrs, I am driving V1: GBF1478T to perform delivery services. At that point of time, I was travelling along Jurong Island Highway at a speed of about 60km/h. There were 4 lanes, and I was travelling on the second lane from the left. The traffic was clear and while I was approaching a bend, I saw that there was a stationary vehicle (Breakdown) on the same lane, immediately I pressed on the break. However, due to the wet floor, V1 couldn't stop in time resulted the front of V1 to collide onto the rear of V2: 59122MID. (Lamp Post 71 & 72).

Subsequently, I went down to take photos of the accident and tow-truck had towed V1. No one was injured and there was no traffic police or ambulance came to scene. V1 does not have any in-vehicle camera. V1's front part was badly damaged. That is all.





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 3 of 3 Report No. T/20230504/2042

CONTINUATION OF REPORT

Signature of Officer Recording The Report:
J /
SGT 2 LUI WENG SOON

A ST

Signature Of Interpreter: Not applicable

Officer In Charge Of Case: TP / GIA / SI ANG YI TING, STEPHANIE Contact No.: 65476414 Signature Of Informant:

لنعه

Date/Time: 04/05/2023 12:14

Classification Of Case:

NP168

20 McCallum Street, #09-01 Tokio Marine Centre Singapore 069046

VEHICLE DAMAGE INSPECTION REPORT

kio Marine Insurance Singapore Ltd

McCallum Street, #09-01 Tokio Marine Centre

gapore 069046

Our File No:

M2302820

Date:

07/06/2023

FERENCE

ured/Claimant: te of Loss:

KJM CURRY HOUSE & RESTAURANT PTE LTD

Policy No:

MP003366

Nature of Claim:

OD

Claim No: M2302820

SCRIPTION & IDENTIFICATION OF VEHICLE

03/05/2023

g No: ike & Model:

g. Date:

GBF1478T

TOYOTA DYNA 150, 3.0 D (M) 08/07/2016 (Man. Year: 2016)

Engine No: Chassis No: 1KD2596902

lour: White

Odometer:

KDY2318023876 39142 km

gine Capacity: irket Value/New Car Price: 2982 cc

N/A

m Insured (S\$):

Market Value/New Car Price

INDITION OF VEHICLE AT THE TIME OF SURVEY

neral Condition:

Poor Yes

Steering (Serviceable): Engine Modification:

Yes No

Footbrake (Serviceable): Pre-accident Condition:

Yes

Good

INDITION OF TYRES

ndbrake (Serviceable): ont Tyre Size:

195R15C

Rear Tyre Size:

195R15C

GREEN-MAX 80 mm

ont Left Side: ont Right Side: GREEN-MAX 80 mm GREEN-MAX 80 mm Rear Left Side: Rear Right Side:

GREEN-MAX 80 mm

above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff
12,916.90	12,278,90	638.00	4
11.00	11.00	0.00	0
2,300.00	1,350.00	950.00	41
1,200.00	800.00	400.00	33
0.00	0.00	0.00	
16,427.90	14,439.90	1,988.00	12
	11,550.00		
0.00	600.00	-600.00	
16,427.90	10,950.00	5,477.90	33
1,314.23	876.00	438.23	33
17,742.13	11,826.00	5,916.13	33
	12,916.90 11.00 2,300.00 1,200.00 0.00 16,427.90 0.00 16,427.90 1,314.23	12,916.90	12,916.90 12,278.90 638.00 11.00 11.00 0.00 2,300.00 1,350.00 950.00 1,200.00 800.00 400.00 0.00 0.00 0.00 16,427.90 14,439.90 1,988.00 11,550.00 600.00 -600.00 16,427.90 10,950.00 5,477.90 1,314.23 876.00 438.23

SPECTION

te of Assignment:

te Inspected:

juster:

08/05/2023 Present Location:

IN-OD-GBF1478T-Ban Choon Motor Works (HQ)-Blk 3 Pioneer Road

North #01-15, 628457 Jurong West-Tel: 62641191

08/05/2023 Inspected At:

Ban Choon Motor Works (HQ) Blk 3 Pioneer Road North #01-15

Singapore 628457

timated Period of Repair:

Dennis Ho

10.0 days

Manager: Lim Chai Lim Emily

TE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability ler any other circumstances is hereby expressly excluded.

LI AIL DE IAILO

eference

irt Source: (Last Synchronised: 07 Jun 2023)

irts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

ıbour: Repairer's (Price-denominated Standard List)

int Code: Tokio Marine Insurance Singapore Ltd/GBF1478T/07/06/2023 11:33

Ilidity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page


irther Info: Items/values not in reference catalogue are prefixed with an asterisk *.

ecommended Parts

. Qty Part No.	Particulars	Condition	Repairer's	Amount
1	*Front Windscreen	Broken	480.00 F	*480.00
1	*Front windscreen rubber	Necessary	10.00 F	*10.00
1	*Dashboard	Broken	480.00 F	*480.00
1	*Wiper panel	Dented	150.00 F	*150.00
2	*Wiper arms	Bent	150.00 F	*150.00
2	*Wiper blades	Necessary	72.00 F	*72.00
1	*Wiper motor	Damaged	420.00 F	*420.00
2	*Wiper covers	Damaged	20.00 F	*20.00
1	*Front panel	Dented	450.00 F	*450.00
1	*DYNA emblem	Necessary	42.00 F	*42.00
1	*Front grille	Broken	160.00 F	*160.00
1	*Front grille logo	Broken	50.00 F	*50.00
2	*Headlamps	Broken	840.00 F	*840.00
2	*Front fenders	Dented	240.00 F	*240.00
1	*LH side mirror - complete	Bent	210.00 F	*210.00
1	*Centre garnish (BLACK)	Cracked	140.00 F	*140.00
2	*Side garnishs (BLACK)	Cracked	120.00 F	*120.00
2	*Front door pillars	Bent	840.00 F	*840.00
1	*LH front door rear pillar	Bent	180.00 F	*180.00
1	*LH arch panel top garnish	Cracked	120.00 F	*120.00
2	*Front doors	Bent	1,440.00 F	*1,440.00
1	*LH front door garnish	Cracked	110.00 F	*110.00
1	*LH front door channel	Cracked	120.00 F	*120.00
1	*LH front door window glass	Cracked	210.00 F	*210.00
1	*LH front door cardboard	Cracked	420.00 F	*420.00
1	*LH front door glass regulator	Bent	125.00 F	*125.00
1	*LH front door inner lock	Bent	140.00 F	*140.00
1	*LH front door glass outer moulding	Broken	75.00 F	*75.00
1	*Front door hinges	Bent	45.00 F	*45.00
1	*Coolng coil	Broken	1,450.00 F	*1,450.00
1	*Receiver drier	Broken	120.00 F	*120.00
1	*Washer tank	Cracked	160.00 F	*160.00
1	*Radiator	Serviceable	580.00 F	Serviceable
1	*Steering shaft	Bent	1,200.00 F	*1,200.00
1	*ERP bracket	Necessary	26,00 FS	*26.00
pplementary #1				
1	*Air con condenser	Dented	350.00 F	*350.00
ranchise part, S=SpcNet				
		Sub Total (S\$)	11,745.00	11,165.00
	+ M	argin on L,N Items 10.00/10.00% (S\$)	1,171.90	1,113.90
		Total Parts (S\$)	12,916.90	12,278.90

Qty Particulars		Repairer's	Amo
scellaneous Items			
1 OD/TP Case (Insurer)		11.00	11
	Sub Total (S\$)	11.00	11
ecommended Labour			
Particulars Particulars	Lab.Type	Repairer's	Amou
intwork Labour			
To putty and spray painting on accident damaged parts. bour Items	New	1,200.00	800.
To dismantle and reassembe of front windscreen	New	100.00	0.
To dismantle and reassemble of air con unit and refill of air con gas	New	120.00	100.
To dismantle and reassemble of dashboard	New	280.00	150.
To knocking and straghtening of all accident damaged parts. To changing of the above parts.	New	1,800.00	1,100.
Gross Labo	our Cost (S\$)	3,500.00	2,150.

< END OF ESTIMATES >







3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

1/32: Chassis Number

2/32: Front View 1










3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

4/32: Front View Right 3

5/32: Front View Left 4








3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

8/32: Front View 7







3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

11/32: Front View 10







3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

14/32: Front View 13








3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

17/32: Front View 16







3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

20/32: Front View 19








3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

23/32: Front View 22







3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

26/32: Front View 25







3F1478T - Submitted by: Tokio Marine Insurance Singapore Ltd (Internal Surveyor)

29/32: Front View 28





31/32: Photo After Spray 30

32/32: Photo After Spray 31

Tokio Marine Insurance Singapore Ltd.

Company Reg. No.: 192300014M) (GST Reg No.: M2-0000023-4)

O McCallum Street #09-01 Tokio Marine Centre Singapore 069046

: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com



member of the oklo Marine Group

Our Reference

: M2302820

Date

: 07-Jun-2023

Ban Choon Motor Works Blk 3 Pioneer Road North #01-15 Singapore 628457

Dear Sir

REPAIRS TO VEHICLE NO

: GBF1478T

OWNER

: KJM CURRY HOUSE & RESTAURANT PTE LTD

POLICY NO

: MP003366

We refer to the inspection of the above accident vehicle and confirm that you may proceed with the repairs to the damages sustained for the amount as shown below. This offer is subject to the vehicle being satisfactorily repaired.

Cost of Repairs before GST	S\$	11,550.00
Less Excess	S\$	600.00
Nett Amount before GST	S\$	10,950.00
+ GST 8.00%	S\$	876.00
Nett Amount	S\$	11,826.00

Please retain all the damaged parts for our inspection/collection and submit your final bill, photographs of the repaired vehicle and Satisfaction & Subrogation Note duly signed by the Insured upon completion of repairs.

Should we receive complaints from our Insured/Owner within 21 days after taking delivery of the said vehicle from your workshop, we reserve the right to hold your payment until the vehicle is satisfactorily repaired.

Yours faithfully,

CLAIMS DEPARTMENT

ease note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject to the Personal Data Protection licy Statement posted at www.tokiomarine.com

CLAIM NO:

SATISFACTION CUM DISCHARGE VOUCHER

TO: TOKIO MARINE INSURANCE SINGAPORE LTD

I/We hereby declare that the repairs of my/our motor vehicle registration No.

GBF 1478 T have been completed to my/our satisfaction and I/we agree

that the payment for the sum of \$11826.00 to the repairer for such

repairs shall be in full discharge of my/our claim under Policy No. MP003366

in respect of the damages caused to my/our motor vehicle in the accident which

occurred on 3 5 23

Date: 22/5/23

Signature (Insured)



NRIC:



Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg. No.: M2-0000023-4)

TOKIO MARINE INSURANCE SINGAPORE LTD

10.07.2023 4628 00972177





N200125C

1.00pm



