

REPAIR ESTIMATE*

VEHICLE NO SH080481A

=04.05.2023

MAKE REG. 29.04.2021

MODEL IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>Return</i>			\$459.40
1	REAR BUMPER CENTRE MOULDING <i>cr</i>			\$451.25
1	REAR BUMPER REINFORCEMENT ? <i>nn</i>			\$394.80
2	REAR BUMPER STAY LH/RH ? <i>nn</i>		\$138.10	\$276.20
10	REAR BUMPER CLIPS <i>mc</i>		\$2.20	\$22.00
1	BOOTLID COVER <i>ScRXR</i>			\$2,549.70
1	BOOTLID H EMBLEM <i>mc</i>			\$38.00
1	BOOTLID EMBLEM IONID <i>mc</i>			\$31.80
1	BOOTLID EMBLEM HYBRID <i>mc</i>			\$24.30
1	BUMPER FOG LAMP ? <i>nn</i>			\$201.50
2	BUMPER NUMBER LAMP LH/RH ? <i>nn</i>		\$42.65	\$85.30
1	BUMPER HOOK COVER <i>X</i> <i>nn</i>			\$94.60
2	REAR BUMPER BRACKET LH/RH ? <i>nn</i>		\$55.80	\$111.60
			1026.75	\$4,740.45
			205.35	\$948.09
	20.00% DISCOUNTED TOTAL			\$3,792.36
1	BOOTLID COMFORT APP STICKER <i>mc</i>			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER <i>mc</i>		\$30.00	\$60.00
1	REAR BUMPER MAT <i>mc</i>			\$50.00
1	REAR NUMBER PALTE W/HOLDER <i>cr</i>			\$55.00
1	REAR REVERSE SENSOR ? <i>nn</i>			\$180.00
				\$301.50
	Labour Charge			\$850.00 <i>700</i>
	Panel Beating			\$600.00 <i>500</i>
	Spray Painting Charge			\$60.00 <i>30</i>
	Check wiring and lighting			\$200.00 <i>80</i>
	Remove/Refix Windscreen big/ small			\$60.00 <i>X</i>
	Tuff Kote <i>nn</i>			\$60.00 <i>70</i>
	Remove/Refix reverse sensor			\$1,830.00
				\$5,923.86
	ESTIMATE TOTAL			
	Total P/P = 2366.40		Total = 2366.40	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.				

3 days P/P 8/10/23
5/5/23 330pm