

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0483/2023/EQ
DATE : 18-May-23
WIP : 21300

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS AMEERA BINTE SAPIEE
ADDRESS : BLK 136 SIMEI STREET 1
#11-74
SINGAPORE 520136
TELEPHONE : HP +65 91529591
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220147158
VEHICLE NO : **SKZ 4649 K**
MODEL CODE : AUDI Q3 1.5 TFSI S-TRONIC
MODEL YEAR : 13/12/2022
ENGINE NO : DFY 358651
CHASSIS NO : WAUZZZF38P1020582
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-May-23
PLACE OF ACCIDENT : OUTSIDE JEWEL CHANGI AIRPORT CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKZ 4649 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,500.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 6,372.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKZ 4649 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,445.00	
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 140.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 256.00	
4	FRONT BUMPER LOWER GRILLE COVER PLATE	1	\$ 61.00	
5	FRONT BUMPER GRILLE - LH / RH	2	\$ 262.00	
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 224.00	
7	FRONT BUMPER SPOILER	1	\$ 451.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 362.00	
9	RADIATOR GRILLE	1	\$ 1,690.00	
10	RADIATOR GRILLE STRIKER PLATE	1	\$ 288.00	
11	RADIATOR GRILLE COVER CAP	1	\$ 49.00	
12	RADIATOR GRILLE BRACKET	1	\$ 51.00	
13	RADIATOR GRILLE SECURING PLATE	1	\$ 39.00	
14	FRONT "360" CAMERA	1	\$ 1,326.00	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 121.00	
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,030.00	
17	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 92.00	
18	FRONT BUMPER TOP COVER	1	\$ 145.00	
19	CAUTION SIGN STICKER	1	\$ 17.00	
20	AIR CONDITIONER STICKER	1	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 9,058.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKZ 4649 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
22	FRONT PARKING AID SEAL RING	4	\$ 11.00	
23	HORN HIGH TONE - LH	1	\$ 157.00	
24	HORN LOW TONE - RH	1	\$ 149.00	
25	HORN BRACKET - LH / RH	2	\$ 52.00	
26	BONNET	1	\$ 3,765.00	
27	BONNET IMPACT PROTECTION - CENTER	1	\$ 34.00	
28	BONNET STRIKER - LH / RH	2	\$ 260.00	
29	BONNET LOCK - LH / RH	2	\$ 481.00	
30	BONNET RELEASE ELEMENT	1	\$ 69.00	
31	BONNET RELEASE LEVER	1	\$ 17.00	
32	BONNET BOWDEN CABLE - CENTER	1	\$ 67.00	
33	BONNET RELEASE CABLE COVER	1	\$ 12.00	
34	HEADLIGHT MOUNTING - LH / RH	2	\$ 280.00	
35	HEADLIGHT - LH / RH	2	\$ 12,610.00	
36	LIFT CYLINDER - LH / RH	2	\$ 488.00	
37	LIFT CYLINDER HOSE	1	\$ 96.00	
38	FRONT WHEEL COVER - LH / RH	2	\$ 598.00	
39	RADIATOR AIR GUIDE - LH / RH	2	\$ 94.00	
40	RADIATOR AIR GUIDE - UPPER	1	\$ 61.00	
SUB TOTAL SPARE PARTS		:	\$ 19,844.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKZ 4649 K**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - LOWER	1	\$ 53.00	
42	FRONT NUMBER PLATE	S/N	\$ 60.00	
43	SUNDRIES		\$ 600.00	
TOTAL SPARE PARTS		:	\$ 29,615.00	
TOTAL LABOUR CHARGES		:	\$ 6,372.00	
GRAND TOTAL		:	\$ 35,987.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT