



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 3762L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER SIDE HOLDER	DAMAGED	102.00	102.00
1	FRONT BUMPER LOGO	NECESSARY	78.00	78.00
1	FRONT BUMPER SENSOR	DAMAGED	265.00	265.00
4	FRONT BUMPER HOLDER @\$25.00	NECESSARY	100.00	100.00
1	FRONT BUMPER NOZZLE COVER	MISSING	43.00	43.00
1	FRONT BUMPER NOZZLE PUMP	MISSING	214.00	214.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	558.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	188.00	-
1	HEADLAMP	CUT	3,068.00	3,068.00
1	HEADLAMP ECU	NOT NECESSARY	945.00	-
1	FRONT FENDER	NOT NECESSARY	770.00	-
1	FRONT FENDER EMBLEM	NOT NECESSARY	82.00	-
1	BONNET	NOT NECESSARY	1,379.00	-
	LESS 5% DISCOUNT		-389.60	-
	LESS 10% DISCOUNT		-	-387.00
			7,402.40	3,483.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER (SN)	DISTORTED	2,500.00	1,700.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER SIDE GRILLE (SN)	NOT NECESSARY	380.00	-
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	1,200.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	300.00	-
			4,430.00	1,750.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING.		800.00	250.00
	WIRING.		100.00	30.00
	TO APPLY TUFF COAT.	NOT NECESSARY	150.00	-
	TO REMOVE FRONT BUMPER SENSOR .		100.00	50.00
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	200.00	-

Report Ref No. CS/AGI23005087/Any3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			2,300.00	680.00
GRAND TOTAL			14,132.40	5,913.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CS/AGI23005087/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.