

AUTOMOBILE HUB

VEHICLE DETAILS

VEHICLE NO : SLQ6869P 2017 JULY
 VEHICLE MODEL : TOYOTA CHR
 CHASSIS NO : ZYX102039928

TP 1st Cap.
 Veron.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Delint</i>	1	\$ 855.10	\$ 855.10
2	REAR BUMPER SIDE HOLDER <i>new</i>	1	\$ 112.20	\$ 112.20
3	REAR BUMPER LOWER GARNISH <i>new</i>	1	\$ 465.10	\$ 465.10
4	REAR FENDER WHEEL ARC GARNISH <i>ht</i>	1	\$ 195.20	\$ 195.20

Rear Bumper Side Grille.
cut

187.
✓

TOTAL PRICE: \$ 1,627.60
 LESS 25% *1237.30* \$ 406.90
 SUB TOTAL PRICE: *927.97* \$ 1,220.70

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER WHEEL ARC GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	REAR TYRE <i>new</i>	1	\$ 280.00	\$ 280.00
4	REAR WHEEL RIM <i>ht</i>	1	\$ 880.00	\$ 880.00

550

TOTAL : \$ 1,210.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	<i>200</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
5	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>	

TO \$ 1,100.00

560

ESTIMATE REPORT

TOTAL PARTS COST:

\$ 2,430.70

TOTAL LABOUR COST:

TOTAL REPAIR COST:

LKK Auto Consultants hence notify the Repaired of the ~~1,100.00~~ *3,530.70*
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

total: 2037.97
4/52 1.6/K
03 Days