

Name & Address:

Motor Claims Department
ALLIANZ INSURANCE (S) PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

Email/Fax No:

Contact No:

Vehicle No:

EJ7171G

Brand & Model:

PORSCHE MACAN

Chassis/VIN No:

WP1ZZZ95ZHLB21316

Date:

17-May-23

Franchise:

PORSCHE MACAN

Contact Person (Eurokars):

VICTOR

Type of Claim:

THIRD PARTY

YEAR MODEL:

20/06/2016

WIP#:

46366

Contact No (Eurokars):

6331 0680
PARTS / MATERIAL CHARGES
MARK = Survey Marking [Key "A" If item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	LID (front bonnet)	P95B-823-031-LY-GRV	1		-	\$ 4,224.80
2	GASKET for engine cover	P95B-823-739- -	2		-	\$ 19.20
3	HOOD LATCH lock	P95B-823-509-B -	2		-	\$ 294.00
4	COVER (trim engine bay)	P95B-805-806-N -1E0	1		-	\$ 93.30
5	COVER (headlamp trim LH)	P95B-807-173-A -1E0	1		-	\$ 65.90
6	COVER (headlamp trim RH)	P95B-807-174-A -1E0	1		-	\$ 65.90
7	EXPANSION RIVET (for trim engine)	PPAF-004-750- -	4		-	\$ 11.60
8	EXPANSION RIVET (for trim cover bonnet)	P95B-863-151- -	15		-	\$ 349.50
9	WARNING SIGN	P7PP-010-006-A -	1		-	\$ 6.60
10	START/STOP WARNING SIGNSTICKER	P7PP-010-786-T -	1		-	\$ 72.60
11	PORSCHE CREST	P9P1-853-601- -	1		-	\$ 292.00
12	DESK PAD CREST	P9P1-853-611- -	1		-	\$ 18.60
13	HOOD BADGE NUT	PWHT-004-974- -	2		-	\$ 4.00
14	LOGO "PORSCHE" REAR CHROME	P95B-853-687- -	1		-	\$ 170.40
15	LOGO "MACAN" CHROME	P95B-853-675- -	1		-	\$ 117.50
16	LOGO "S" CHOME REAR	P95B-853-675-A -	1		-	\$ 85.20
17	LINING (front bumper)	P95B-807-221-A -G2X	1		-	\$ 1,362.10
18	BUMPER, REAR	P95B-807-417-K -G2X	1		-	\$ 1,226.00
19	CAP rear bumper	P95B-807-500-A -G2X	1		-	\$ 50.00
20	SPOILER	P95B-807-521-AA-1E0	1		-	\$ 355.70
21	COVER (bumper trim)	P95B-807-834-K -1E0	1		-	\$ 237.20
22	EXPANDER NUT	PWHT-004-935- -	8		-	\$ 13.60
23	SUPPORT (bracket bumper LH)	P95B-807-253-C -	1		-	\$ 89.20
24	SUPPORT (bracket bumper RH)	P95B-807-254-H -	1		-	\$ 124.80
25	SENSOR bumper	P5Q0-919-275-B -G2X	4		-	\$ 1,120.80
26	GASKET bumper sensor	P5Q0-919-133- -9B9	4		-	\$ 13.60
27	DAMPING PART LH (sound absorber)	P95B-805-885- -	1		-	\$ 41.80
28	DAMPING PART RH (sound absorber)	P95B-805-886- -	1		-	\$ 41.80
29	REINFORCEMENT	P8R0-807-313-D -	1		-	\$ 374.30
30	SUPPORT LH reinforcement	P8R0-807-331-B -	1		-	\$ 140.20
31	SUPPORT RH reinforcement	P8R0-807-332-E -	1		-	\$ 125.90
32	REAR LID (rear bonnet)	P95B-827-025-LY-GRV	1		-	\$ 2,838.60
33	STOP BUFFER	P95B-827-239- -	2		-	\$ 76.00
34	STOPPER STOP PLATE	P958-512-475-00-	1		-	\$ 3.80
35	BLIND RIVET NUT	PPAF-906-481- -	4		-	\$ 24.40
36	Retaining strip for spoiler	P95B-827-933- -	1		-	\$ 57.30
37	BLIND RIVET	PPAF-016-206- -	10		-	\$ 71.00
38	CAP cover	P958-512-975-00-	2		-	\$ 4.00
39	CAP cover	P958-512-976-00-	2		-	\$ 4.00
40	Blind rivet screw	P9A7-005-207-00-	3		-	\$ 28.80
41	HINGE LH	P8U0-827-299-A -	1		-	\$ 71.60

42	Hinge RH	P8U0-827-300-A -	1		-	\$ 76.00
43	COUNTERSUNK-HEAD SCREW	PN -907-448-05-	2			\$ 6.20
44	OVAL-HEAD SCREW	PN -101-961-03-	2		-	\$ 4.40
45	REAR WINDOW GLASS	P95B-845-051-AT-	1		-	\$ 2,082.10
46	GASKET	P95B-845-571- -	1		-	\$ 67.70
47	ADHESIVE SET	P000-043-305-35-	1		-	\$ 464.40
48	REAR LIGHT (RH) outer	P95B-945-096-R -	1		-	\$ 800.40
49	REAR LIGHT (RH) INNER	P95B-945-094-T -	1		-	\$ 644.80
50	REFLECTOR REAR (LEFT)	P95B-945-725-AB-	1		-	\$ 348.10
51	REFLECTOR REAR (RH)	P95B-945-726-AB-	1		-	\$ 348.10
52	Alloy wheel silver	P95B-601-025-EQ-88Z	1		-	\$ 2,058.80
53	SENSOR TPM (433MHz)	PPAB-907-275- -	1		-	\$ 358.10
54	ALU TYRE PRESS VALVE (W	P9P1-601-361-F -	1		-	\$ 72.40
55	REAR MUFFLER RH	P95B-253-600-FY-	1		-	\$ 2,239.80
56	REAR MUFFLER LH	P95B-253-611-AY-	1		-	\$ 2,111.70
57	CLAMPING SLEEVE	PPAB-111-220-A -	2		-	\$ 208.80
58	TAIL PIPE right inner	P95B-253-682-C -	1		-	\$ 240.00
59	TAIL PIPE right outer	P95B-253-682-D -	1		-	\$ 240.00
60	LENS-HEAD SCREW	P9A7-008-019-00-	4		-	\$ 14.40
61	TAIL PIPE left inner	P95B-253-681-C -	1		-	\$ 240.00
62	TAIL PIPE left outer	P95B-253-681-D -	1		-	\$ 240.00
63						\$ -
64						\$ -
65						\$ -

Sub-Total (Parts Price) \$ - \$ 27,253.80

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRONT BUMPER/BONNET/REAR BUMPER/BONER/REINFORCEMENT.TO TRANSFER ALL MECHANISM TO NEW PART. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 9,360.00
2	TO RESPRAY FRONT BUMPER/BONNET & REAR BUMPER/BONNET.		\$ 5,600.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	TO SUPPLY REAR LICENCE PLATE WITH CASING	nett	\$ 70.00
6	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET	nett	\$ 150.00
7	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	nett	\$ 1,560.00
8	TO REPLACE 1 PC TYRE. 235/55 R19	nett	\$ 980.00
9	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	nett	\$ 120.00
10	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	nett	\$ 680.00
11	TO TRANSFER THE TAILGATE / DOOR MECHANISM.	nett	\$ 780.00
12	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	nett	\$ 560.00
13	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	nett	\$ 195.00

14	TO SUPPLY SOLAR FLIM ON THE REAR WINDSCREEN GLASS.	nett	\$ 300.00
15	TO TRANSFER / SUPPLY THE REVERSE SENSORS.	nett	\$ 500.00
16	TO TRANSFER / SUPPLY THE REVERSE CAMERA.	nett	\$ 400.00
17	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00
18	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
19	SUNDRIES.	nett	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 22,755.00

		<u>REVISED</u>	<u>PRICE</u>
Parts Price	\$	-	\$ 27,253.80
Labour Price	\$	-	\$ 22,755.00
Total (Initial Estimate)	\$	-	\$ 50,008.80
Supp 1	\$	-	\$ -
Supp 2	\$	-	\$ -
Supp 3	\$	-	\$ -
Total (Before Excess)	\$	-	\$ 50,008.80
Less Excess	\$	-	\$ -
TOTAL (After Excess)	\$	-	\$ 50,008.80
GST 8%	\$	-	\$ 4,000.70
GRAND TOTAL	\$	-	\$ 54,009.50