## **COMFORT TRANSPORTATION PTE LTD**

REPAIR ESTIMATE

Vehicle No.: SH 9418C

Make : HYUNDAI

Model : 1-40

Date: 27/04/2023 Insurance: INCOME

MVA: MS. LOKE YY

Oty	Parts Description / Labour	Туре	Unit Price	Amount
1 10 1 1	HEADLAMP LH SC FRONT BUMPER COVER SC FRT BUMPER CLIPS NO FRT BUMPER SIDE BRACKET LH RAW FRT FENDER LH BULL FENDER RETAINER LH FRT WHEEL HUB CAP LH SCY FRT WHEEL RIM LH PUT SUB TOTAL LESS 20%		3993	\$ 1,388.00 \$ 1,052.20 \$ 22.00 \$ 24.60 \$ 663.00 \$ 24.60 \$ 217.20 \$ 650.60 \$ 3,391.60 \$ 678.32 \$ 2,713.28
	Labour Charge PANEL BEATING SPRAY PAINTING CHARGE CHECK ALL LIGHTING TOTAL LABOUR		3194.40	\$ 560,600.00 \$ 500,600.00 \$ 30,600.00 \$ 1,260.00 \$ 3,973.28
	ESTIMATE TOTAL	Mo:	85688	\$ 3,973.28

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

32m/s = 3427.52 × 3400/ 21/5 / 11/2m 27/4/23 330pm