

COMFORTDELGRO ENGINEERING PTE LTD

✓ SAS-KV → see attached

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK

DATE: 08.05.2023

SNF1398Z

MODEL: Hyundai i40

INSURANCE: CHINA TAIPING (4S)

MVA: LIM T S

VEHICLE NO.: SHD3135J

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper Sur X R	1		\$ 553.00
	Rear Bumper Under Cover Sur	1		\$ 228.00
	Rear Bumper Clips X MV	10	\$ 2.20	\$ 22.00
	SUB TOTAL			\$ 803.00
	LESS 20%			\$ 160.60
	DISCOUNTED TOTAL			\$ 642.40
	Reverse Sensors ? X NN	1		\$ 135.70
	LESS 10%			\$ 13.57
	S/NETT TOTAL			\$ 122.13
	Rear Bumper Mat NCC	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 814.53
	Labour Charge			\$ 300.00
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 120.00
	R/I Reverse Sensors			
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 1,534.53

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

T = 792.40 2 days  
= 633.92 C/S  
≈ 650  
9/5/23  
4pm