



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

SUPPLEMENTARY

## ESTIMATE FOR SFP2829H

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT  
6 RAFFLES QUAY  
#21-00  
SINGAPORE 048580  
65073848

WIP No 10074  
Reg No/Reg Date SFP2829H / 18/07/2017  
Date In/Mileage 19/06/2023/ 102071  
Chassis No WDD2130422A232729  
Engine No 27492030991553  
Make/Model M6/MB E 200 2.0 SEDAN (W213) "AVANTGARDE  
Colour/Trim 027 775 Iridium sil/ 042 214 Leather Haz

### Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	07/07/2023/ 14:55	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LEFT REAR BASIC MOUNTING FOR BUMPER	1.00	40.84	00.00	40.84
X RIGHT REAR BASIC MOUNTING FOR BUMPER	1.00	40.84	00.00	40.84
X RIGHT REAR BASIC MOUNTING FOR BUMPER	1.00	76.02	00.00	76.02
X LEFT REAR BUMPER BOTTOM BRACKET	1.00	46.81	00.00	46.81
X LEFT REAR BASIC MOUNTING FOR BUMPER	1.00	74.45	00.00	74.45

ESTIMATE

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

8% GST on **Nett 278.96**  
**Total Payable 301.28**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG