Our Job Ref No         :         305553907           Date         :         11.05.2023				ENGINEERING -				
				ComfortDelGro Engineering Pte Ltd				
FINA	LIZATION FORM			59 Loyang Fax: 6546	Drive Singapore 508969 8156			
To :LKK				_ Fax :				
Attn	: <u>IR</u>	FAN						
Vehi	cle Reg No. : SHD350	01K	Dat	e of Accident;	06.05.2023			
The	survey and estimates of the	repairs of the abo	ve-mentioned	vehicle are as fo	llows:-			
1.	The repair job shall bill to	: CHIN	NA TAIPING		SLF6189B			
2.	The finalized amount sha	II be:						
	(a) Spare Parts after I	ist discount				_		
	(b) Labour Charges	(include advertisen	nent stickers e	tc,if any)		_		
	Total for Part-By-					<del></del> .		
	(c.) Lumpsum Repair ( Total for Lumpsum Final Lumpsum F	n repair cost after L	ess: 20%		\$ <del>2,350.00</del> 2	4300.00 4300.00		
3. 4.	Estimated normal period  We shall treat the above within 7 working days	re amount as Corr	ect and Confi					
<ol><li>Thank you for your assistance.</li></ol>			• •	We confirm the estimates and finalized amount				
	Signature : LIM T S  Tel : 62148398  Fax : 65468156		N.	Signature:  Name:				
Fo	r Official Use Only			Appendix of the Control of the Contr	The second second second	<del>-</del> ;		
	Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
1.	Rental Rate P/Day		YES					
2.	Loss of Income Paid		N			4		
-	Survey Fees	****	-	ar satural	-	1		
5.	LTA Search Fee / GEARS  Medical Fees (on behalf of driver, if applicable)  Overrun	\$26.75 / \$2.00	Y			1		

Remarks:

**COMFORTDELGRO** 

## **COMFORTDELGRO ENGINEERING PTE LTD**

## REPAIR ESTIMATE

DATE:

08.05.2023

INSURANCE: CHINA TAIPING

MODEL:

Hyundai i40

MVA: LIMTS

VEHICLE NO .: SHD3501K

RT NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
79A .	Front Bumper Ser X & 1CRA	1		\$ \1,052.20
1321A	Front Bumper Clips X / NEC	10	\$ 2.20	$\sqrt{22.00}$
	Front Bumper Brkt LH ? X SVC	1		\$ 22.40
	Front Fender LH Sen+	1		\$ 663.00
28346	Front Fender Shield LH? / DEF	1		\$ 174.90
2019	HeadLamp LH ? X S V C	1		\$ 1,388.00
	Front Wheel Cap LH ( )a	1	1 1	\$ 217.20
	Tronk times eap zitt t		1954.20	
	SUB TOTAL			\$ 3,539.70
•	LESS 20%		1703.44	\$ 707.94
	DISCOUNTED TOTAL			\$ 2,831.73
	Labour Charge			
	Panel Beating			\$ 600.00
	Spray Painting Charge		-	\$ 600.00
	Check Lightings			\$ 40.00 \$ 40.00
	Tuff Kote			\$ 40.00 \$ 120.00
	Wheel Alignment		1180.00	\$ 60.00
	Towing Fee		1	55/55
	TOTAL LABOUR		1340.00	\$ 1,460.00
	ESTIMATE TOTAL		291344	\$ 4,291.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the

vehicle is surveyed by a motor Surveyor appointed by the insurance company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey beforulafter spray painting
- To dispilay damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

10

2 /5/23 2 pm ff 15hm



ComfortDelGra Engineering Pte Ltd

105 Bodnes Road Siegalion 679761 ( Mainteg - 6, 1938) 6386 Fistariar + 65 8286 9756

Service Contracts
Service Contracts
2015/99/204
History Contracts
1007/99/204
History Contracts





## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: / ( ) Time Receiv	ved: 2.000	3. Vehicle Type:	4. Type of Towing:
2. New SPARK Kak		Private	Normal Tow
Name of Customer : MAR KAZ		Taxi (CTPL/CCPL)	☐ King Dolly
		Fleet	Flat Bed
Contact No. : 984 69	0/0	STK (Boon Lay)	Crane-up
Vehicle No. : SHD 350	21/5-	5. Nature of Service:	6. Parts Replaced/Remarks:
Make/Model/Colour:		Jumpstart Recovery	
Email :		Change Tyre / Battery	
7.1 Ition: TAMB JT	) (		Tow - In Workshop: oky Exhaust
9. Preferred Workshop:			erheating Steering Faulty
Braddell Loy	-	T dilodii	ke Faulty Alternator Faulty
Sin Ming Sun  Komoco (UBI / Leng Kee)	gei Kadut	CD.	rting Problem Loss Power ident Engine Stalled
Others:		Cycle a Carriage (FD)	urn Taxi
10. Odometer Reading :		11. Radio / CD Player	FROM THE PARTY OF
Fuel Level : F 1.	/4 1/2 3/4 E	Faulty Not tested	
Job Attended	A SELECTION OF THE SELE		The state of the s
12. Tow Truck / Recovery Van : VR	GAC GAC	O C OTHERS	9196
Name of Driver :	a-bin		REAR
Vicle No.	AN821	52	#: Cracked X: Dented
Time Dispatch ;	5000	raya yaya da	/: Scatched O: Missing
Time of Arrival	20067		
Time Completed :	2115		Signature of Customer
Cash Invoice Details (if applicable)			
13. Cash Invoice No.			
Customer Acknowledgement	Mary and Section		
A. I have been advised to remove all valuable iter cash cards, spectacles, pen, etc.     B. I understand that any items left behind are at c. Surcharge: Towing fee will be levied if the cus	my own risk and SPARK	Car Care™ will not be held llable for such	losses.
Date	Time	S	Signature of Customer
14. WORKSHOP	agel. Con Markhair - on mainteach & the allege and an annial and the second		
Name of Attending Staff/Guard	Date & Time of	Arrival Signat	ure of Attending Staff/Guard
Hame of Attending Stan Guard	20.7 0 1		WORKSHOP CO