

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ZHU LIANG
 45 STIRLING RD
 #05-436
 SINGAPORE 140045
 TEL: 81399321
 ATTN:

Estimate No: MC1903508
 Date: 18 May 2023
 Policy No: D22MTPV01010512
 Veh Reg No: SLQ2897J
 Make/Model: MAZDA MAZDA3
 SEDAN 1.5 AT EU6

Your Ref No: SLQ2897J
 Claim Type: Third Party → Alliance
 Accident Date: 15/05/2023
 TP Veh Reg No: XD9668J

Not Notched
 1/1/2023
 Repair After Paint
 5 days

Estimate Repair Cost to Vehicle No :SLQ2897J

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN MLDG - CHECK PRICE	1 PC	0.00	✓
2 REAR WINDSCREEN MLDG SIDE - CHECK PRICE	2 PC	0.00	✓
3 REAR WINDSCREEN MLDG LOWER - CHECK PRICE	1 PC	0.00	✓
4 REAR FENDER RH	1 PC	1,262.77	✓
5 REAR FENDER COWLING RH	1 PC	164.78	X
6 REAR FENDER COWLING CLIPS	8 PC	24.00	X
7 REAR BUMPER	1 PC	1,143.51	X
8 REAR BUMPER SIDE RETAINER RH	1 PC	40.55	✓
9 REAR BUMPER CLIPS	10 PC	30.00	X
10 REAR WHEEL HUB + BEARING RH	1 PC	467.37	✓
11 REAR LOWER ARM RH	1 PC	282.78	X
12 REAR SHOCK ABSORBER RH	1 PC	369.34	X
13 SPORTS RIM RHR	1 PC	521.40	✓
		4,306.50	
	Less 10%	430.65	3,875.85
Special Nett			
14 TYRE RHR - CHECK PRICE	1 PC	0.0000	X
15 INNER SEAL	1 PC	20.00	✓
16 WINDSCREEN SEALANT	1 PC	40.00	✓
		60.00	60.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
18 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60/
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
20 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	150.00	100/
21 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	280.00	X
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	X
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/
24 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER RH. TO KNOCK & REPAIR REAR DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	600/
25 TO SPRAY REAR BUMPER, REAR FENDER RH, REAR DOOR RH.	1 PC	600.00	400/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Ah Lim Motor Company

Acknowledged by Repairer
 Signature:
 Date: