

呂
與
張

Loo & Chong Law Corporation

(a law corporation incorporated with limited liability)
GEN 201419899M

52 Chin Swee Road #03-67
Singapore 160052
Tel : (65) 6438 2883
Fax : (65) 6438 2889
Email: mail@loonchong.com

In reply please quote our Reference Number

Our Ref: SH23-067.HLH/L (SFZ 536 M)

17 May 2023

BY EMAIL & PDX ONLY

mt.doc@mail.life.hsbc.com.sg

WITHOUT PREJUDICE



HSBC Life (Singapore) Pte Ltd
20 Pasir Panjang Road
#11-00 Mapletree Business City
East Lobby
Singapore 117439
Motor Claims Dept
(Vehicle No. SH 8096 D)

Comfort Transportation Pte Ltd
383 Sin Ming Drive
GAS Building
Singapore 575717

Tan Boon Kiat
Blk 52 Toa Payoh Lor 6
#09-14
Singapore 310052

Dear Sirs,

**TRAFFIC ACCIDENT INVOLVING YOUR INSURED'S VEHICLE SH 8096 D AND SFZ 536 M ON 20 JUNE 2022
AT/ALONG THE BKE - CHANGI**

We act for the claimant **Chue Swee Chin**, the owner of the above said motor vehicle no. **SFZ 536 M**.

We are instructed to claim damages against you/your driver/our insured in connection with the above-captioned accident involving our client's vehicle registration number **SFZ 536 M** and vehicle registration number **SH 8096 D** driven by you/your driver/your insured at the material time.

We are instructed that the accident was caused by you/your driver's/your insured's negligent driving and/or management of motor-vehicle **SH 8096 D**. As a result, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as stated in Part 1 of the Annexure.

A copy each of the supporting documents as stated in Part 2 of the Annexure is enclosed.

We have on **22 June 2022** notified your insurer (abovenamed addressee) of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurer on **23 June 2022 by LKK Auto Consultants Pte Ltd**.

Please note that:

- (a) If you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer;
- (b) you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days of your/your insurer receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer;
- (c) If you have a counterclaim against our client arising out of this accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipts of this letter.

For the avoidance of doubt, unless otherwise indicated, this letter of claim is sent to the abovenamed addressees.

Yours faithfully

Chong Chao Yuan
Loo & Chong Law Corporation

Enc. supporting documents in paragraph 4 enclosed in covering letter to insurers only
Cc: client (via email/fax only) – SFZ 536 M

Our Re: SH22-067.HLH/L (SFZ 536 M)

ANNEXURE

Cost of Repair	\$23,500.00
Rental@3 days	749.00
Survey Report	1,180.00
GIA Reports/LTA, RCB searches	39.00
Incidentals	50.00
Costs Contribution	1,000.00
TOTAL	<u>\$25,518.00</u>

Part 2 – list of supporting documents enclosed in the letter of claim.

LTA search

GIA reports/Police reports & type-written transcripts

repairer's bill and evidence of payments (if any)

rental invoice / agreement

survey report with coloured photographs showing damage to vehicle

the insurer has been notified of the accident and allowed to carry out a pre-repair inspection of claimant's vehicle

correspondence with the potential defendant's insurer relating to pre-repair survey and/or post repair inspection of the claimant's vehicle

Enquire Vehicle Owner Details

Enquire Vehicle Owner Details (As At 20 Jun 2022 / 10:00:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

199303821R

Owner Name:

COMFORT TRANSPORTATION PTE LTD

Registered Address Type:

Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:

383

Registered Street Name:

SIN MING DRIVE

Registered Unit No.:

-

Registered Building Name:

GAS BUILDING

Registered Postal Code:

575717

Vehicle Insurance Details

Vehicle No.:

SH8096D



RECORD MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE

RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 23/06/2022

Your Ref No: SH22-067.HLH/L

Dear Sir/Madam,

Date of Accident: 20/06/2022 00:00 (SGT)

Vehicle No: SFZ536M

Place of Accident: PIE, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SH8096D	PIE, Singapore	(31.00)	1	(28.97)
GST Amount				(2.03)
Total Amount Due (GST Inclusive)				(31.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL:6746 0674 FAX: 6841 7639 HP:96773832 EMAIL: Hup.ley.huat@gmail.com

Chue Swee Chin
1 Kaki Bukit Ave 6
Singapore 417883

Date : 14/05/2023
Vehicle No. : SFZ536M
Make : Honda CRV 2.0
Acc Date : 20/06/2022

Lumpsum Repair

\$ 23,500.00

Singapore Dollars: Twenty Three Thousand and Five Hundred dollars Only.



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO.
CHUA SWEE CHIN 319 PAVILION CIRCLE SINGAPORE 658580

DATE	INVOICE NO.
6/7/2022	A 44875

	VHA NO.	DUE DATE	VEH NO.
	A 44875	6/7/2022	SKC 2493 B
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 20 JUNE 2022 TO 27 JUNE 2022 YOUR REF: SFZ 536 M	7	100.00	700.00
Account Name: BKW RENT A CAR PTE LTD Account No: 118-312-9991 Paynow UEN: 200106276D Bank: UNITED OVERSEAS BANK LTD (UOB) Branch: UOB Shaw Centre Branch Bank Address: 1 Scotts Road #03-04 Shaw Centre Singapore 228208 Bank Code: 7375 Branch Code: 018 Swift Code: UOVBSGSG All cheques must be made payable to BKW RENT A CAR PTE LTD. *Please indicate the invoice number and vehicle number in the reference.	Subtotal		\$700.00
	GST @ 7%		\$49.00
	TOTAL		\$749.00

BKW Rent-A-Car Pte Ltd
120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg
A subsidiary of **BKW Automobile Pte Ltd**



VEHICLE HIRING AGREEMENT

Workshop: _____

HIRER'S PARTICULARS

Name (as in I/C) CHUA SWEET CHIN

NRIC/Passport No: [REDACTED] Date of Birth: _____

Address: 319 PAVILION CIRCLE Age: 65(58580)

Name & Address of Employer _____

Occupation _____ Driving Exp: _____

Driving Licence No: [REDACTED] Passed Date: _____

D/L Type: Local/Int'l/Others: _____

DRIVER'S PARTICULARS

Name (as in I/C) GOH LENG LENG

NRIC/Passport No: [REDACTED] Date of Birth: 14/2/1979

Address: 319 PAVILION CIRCLE Age: 65(58580)

Occupation _____ Driving Exp: _____

Driving Licence No: [REDACTED] Passed / Expiry Date: 20/5/1979

D/L Type: Local/Int'l/Others: _____ Contact No: [REDACTED]

Hirer's Own Vehicle No: 572536M Replace Veh No: _____

Loan Vehicle No: SAC 293B VR No: _____

Make & Model: ACIO Auto/Manual Group: _____

DAILY		WEEKLY/MONTHLY		OTHERS	
Day	Per day	Week	Per week	CDW/PAI	Per day
<u>7</u>	<u>\$700</u>				

Delivery/Collection Svc _____

GST 7% \$49

OR No: _____ (A) SUB-TOTAL \$749

Petrol Level & Surcharge	OUT	E	1/4	1/2	3/4	F	GST

First _____ km FREE per day

Excess mileage is chargeable at _____ cents per km

TOTAL CHARGES _____

INDICATE:
 A - Accidents
 D - Dents
 S - Scratches
 X - Crack



NON WAIVER EXCESS (Subject to GST): \$ 7000

ACCESSORIES CHECK

Data Cards Camera Systems Hub Cap Radio / CD Cartridge

Jack Tyre Opener Petrol-Cap Spare Tyre

Hirer's Signature: _____ Additional Driver's Signature: _____

SINGAPORE Use Only

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given BKW Rent A Car Pte Ltd in connection with this agreement is true.

- ### IMPORTANT
- The Hirer and the authorized driver must be over 23 years of age and under 70 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorised Driver.
 - All vehicles are supplied with petrol and should returned with petrol level likewise. A service charge of \$10 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
 - No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
 - Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
 - Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
 - The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
 - The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace a replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
 - Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$300 - \$500.
 - The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$60.00 per trip.
 - In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
 - The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
 - All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
 - I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
<u>20/02</u>			<u>ANGREN</u>	

Hirer's/Driver Signature _____

Return Of Vehicle: The Hirer Driver Is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"

Date In	Time In	Mileage	Check By	Remarks
<u>22/02</u>		<u>247243</u>	<u>SI</u>	

Hirer's/Driver Signature _____

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Chue Swee Chin
c/o Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

Invoice no.: TP22060026
Date: 02 MAY 2023

Vehicle no: SFZ536M

Model : HONDA CRV 2.0

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 23 JUN 2022 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 1,180.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 1,180.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front & rear** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SFZ536M

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<i>List Items</i>				
1 pc	Front bumper	bent/distorted	\$ 950.00	\$ 950.00
2 pcs	Front bumper side retainer	deformed	\$ 120.00	\$ 120.00
2 pcs	Front bumper side attachment	distorted	\$ 180.00	\$ 180.00
1 pc	Front bumper reinforcement	dent/distorted	\$ 378.85	\$ 378.85
10 pcs	Front bumper clips	necessary	\$ 80.00	\$ 80.00
1 pc	Front bumper air grille garnish	deformed	\$ 215.00	\$ 215.00
1 pc	Front bumper beam	distorted	\$ 165.00	\$ 165.00
1 pc	Rear bumper lower garnish chrome	wrapped/deformed	\$ 750.00	\$ 750.00
4 pcs	Rear bumper lower garnish clips	necessary	\$ 60.00	\$ 60.00
2 pcs	Fog lamp assy	electronically shocked	\$ 350.00	\$ 350.00
2 pcs	Fog lamp cover	grazed/deformed	\$ 220.00	\$ 220.00
1 pc	Front grille	distorted	\$ 580.00	\$ 580.00
6 pcs	Front grille clips	necessary	\$ 90.00	\$ 90.00
2 pcs	Headlamp assembly	electronically shocked	\$ 3,425.70	\$ 3,425.70
2 pcs	Headlamp clips	necessary	\$ 25.80	\$ 25.80
1 pc	Front support panel	dent/distorted	\$ 974.45	\$ 974.45
1 pc	Bonnet	grazed/deformed	\$ 745.00	\$ 745.00
1 pc	Bonnet lock	distorted	\$ 182.10	\$ 182.10
1 pc	Bonnet lock brace Panel	bent/distorted	\$ 177.40	\$ 177.40
1 pc	Air con condenser	bent/distorted	\$ 650.00	\$ 650.00
2 pcs	Air con condenser top mounting	deformed	\$ 80.00	\$ 80.00
2 pcs	Air con condenser bottom mounting	deformed	\$ 80.00	\$ 80.00
1 pc	Radiator assembly	dent/distorted	\$ 725.00	\$ 725.00
1 pc	Tailgate	bent/distorted	\$ 2,250.00	\$ 2,250.00
1 pc	Tailgate lock	bend/distorted	\$ 425.00	\$ 425.00
1 pc	Tailgate lock striker	damaged	\$ 110.00	\$ 110.00
2 pcs	Tailgate stopper	deformed	\$ 90.00	\$ 90.00
1 pc	Tailgate weather strip	wrapped/deformed	\$ 280.00	\$ 280.00
1 pc	Tailgate outer chrome	bend/distorted	\$ 195.00	\$ 195.00
1 pc	Tailgate outer lower garnish	grazed/deformed	\$ 850.00	\$ 850.00
4 pcs	Tailgate outer lower garnish clips	necessary	\$ 80.00	\$ 80.00
1 pc	Tailgate badge	necessary	\$ 85.00	\$ 85.00
1 pc	Tailgate emblem " CRV"	necessary	\$ 65.00	\$ 65.00

Vehicle Number : SFZ536M

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<i>List Items</i>				
1 pc	Tailgate inner trim board	bend/deformed	\$ 675.00	\$ 675.00
8 pcs	Tailgate inner trim board clips	necessary	\$ 80.00	\$ 80.00
2 pcs	Rear number plate lamp	electronically shocked	\$ 90.00	\$ 90.00
2 pcs	Tail lamp	electronically shocked	\$ 748.90	\$ 748.90
2 pcs	Tail lamp sealant	necessary	\$ 120.00	\$ 120.00
4 pcs	Tail lamp clips	necessary	\$ 60.00	\$ 60.00
1 pc	Rear bumper	bend/deformed	\$ 1,250.00	\$ 1,250.00
2 pcs	Rear bumper side retainer	distorted	\$ 120.00	\$ 120.00
2 pcs	Rear bumper side attachment	bent/distorted	\$ 100.00	\$ 100.00
4 pcs	Rear bumper parking sensor cover	deformed	\$ 172.40	\$ 172.40
2 pcs	Rear bumper reflectors	deformed	\$ 242.50	\$ 242.50
10 pcs	Rear bumper clips	necessary	\$ 129.00	\$ 129.00
1 pc	Rear bumper lower garnish	wrapped/deformed	\$ 748.80	\$ 748.80
4 pcs	Rear bumper lower garnish clips	necessary	\$ 60.00	\$ 60.00
2 pcs	Rear bumper side garnish	distorted	\$ 440.00	\$ 440.00
1 pc	Rear end panel	dent/distorted	\$ 781.85	\$ 781.85
1 pc	Rear end top trim	wrapped/deformed	\$ 325.00	\$ 325.00
4 pcs	Rear end top trim clips	necessary	\$ 77.40	\$ 77.40
1 pc	Rear windscreen glass moulding	deformed	\$ 172.80	\$ 172.80
1 pc	Rear windscreen glass inner seal	wrapped/deformed	\$ 38.00	\$ 38.00
14 pcs	Rear windscreen glass clips	necessary	\$ 180.60	\$ 180.60
2 pcs	Rear fender inner trim board	bent	\$ 1,563.60	\$ 1,563.60
16 pcs	Rear fender inner trim board clips	necessary	\$ 206.40	\$ 206.40
1 pc	Rear floor panel	bent/distorted	\$ 972.70	\$ 972.70
1 pc	Rear floor panel under garnish cover	wrapped/deformed	\$ 372.85	\$ 372.85
1 pc	Spare tyre bracket	bent/distorted	\$ 289.90	\$ 289.90
1 pc	Spare tyre adjusting screw	bent/distorted	\$ 178.45	\$ 178.45
1 pc	Spare tyre adjusting screw hook	bent/distorted	\$ 61.10	\$ 61.10
1 pc	Exhaust silencer	disrupted	\$ 781.90	\$ 781.90
3 pcs	Exhaust silencer rubber	wrapped/deformed	\$ 150.00	\$ 150.00
		Parts Sub-Total	\$ 26,823.45	\$ 26,823.45
		Discount 20.00%	\$ 5,364.69	\$ 5,364.69
			\$ 21,458.76	\$ 21,458.76

Vehicle Number : SFZ536M

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 set	Front bumper parking sensor	electronically shocked	\$ 280.00	\$ 250.00
1 pc	Front number plate	distorted	\$ 65.00	\$ 65.00
1 pc	Front number plate casing	deformed	\$ 45.00	\$ 45.00
1 pc	Tailgate outer keyless sensor	electronically shocked	\$ 380.00	\$ 350.00
1 pc	Rear number plate	distorted	\$ 65.00	\$ 65.00
1 pc	Rear number plate casing	distorted	\$ 45.00	\$ 45.00
1 set	Reverse camera	electronically shocked	\$ 680.00	\$ 680.00
1 set	Rear bumper parking sensor	electronically shocked	\$ 280.00	\$ 250.00
1 pc	Rear bumper parking sensor wire	open circuit	\$ 220.00	\$ 220.00
1 pc	Rear windscreen glass sealant	necessary	\$ 120.00	\$ 120.00
Special Nett Sub-Total			\$ 2,180.00	\$ 2,090.00
Spare Parts Total			\$ 23,638.76	\$ 23,548.76

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare Parts Total c/f	\$ 23,638.76	\$ 23,548.76
1	Towing	\$ 120.00	\$ 120.00
2	To tuff coat affected areas	\$ 250.00	\$ 240.00
3	To remove and refix interior upholstery	\$ 250.00	\$ 240.00
4	To remove and refix radiator and top up coolant	\$ 200.00	\$ 180.00
5	To remove and refix air con condenser, piping, vacuum & top up gas	\$ 180.00	\$ 150.00
6	To remove and replace exhaust silencer and straighten exhaust center pipe.	\$ 180.00	\$ 150.00
7	To remove & transfer tailgate mechanism	\$ 250.00	\$ 240.00
8	To reset electrical module system to factory spec.	\$ 180.00	\$ 150.00
9	To adjust chassis alignment on Car O Liner	\$ 250.00	\$ 200.00
10	To respray affected areas	\$ 2,000.00	\$ 1,800.00
11	To renew damaged parts, straighten and repair rear fender inner, front and rear chassis member and aligned all parts	\$ 1,800.00	\$ 1,600.00
12	To remove and refix rear windscreen glass	\$ 180.00	\$ 150.00
13	To remove and refix spare tyre carrier	\$ 180.00	\$ 150.00
14	To check and reconnect snap wiring	\$ 180.00	\$ 150.00
15	To remove and replace reverse sensor & camera	\$ 200.00	\$ 180.00
16	To remove and replace front parking sensor	\$ 180.00	\$ 150.00
	Total	\$ 30,218.76	\$ 29,398.76
	The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :	\$ 23,500.00	

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

Fong Kok Heng
Qualified Appraiser



STOMAX



AU SURVEY

AUTOMAX



AUTOMAX

ATOMAX



AUTOMAX SURVEY

ТОМАХ



ТОМАХ

OMA
11/2



SURVEY



AUTOMAX
SUNWAY




SUNWAY
SURVEY

AUTOMAX SURVEY



SURVEY

COMAL



SURVEY





SURVEY






AUTOMAX





SURVEY



ATOMAX



ATOMAX





OMAX SURVEY



OMAX SURVEY



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 249J

Vehicle Details

Vehicle No.: SFZ536M
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Apr 2023
Vehicle Make: HONDA
Vehicle Model: HONDA CRV 2.0L AT
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: R20A13700152
Chassis No.: JHLRE28309C200183
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$30,057.00
Original Registration Date: 01 Dec 2009
First Registration Date: 01 Dec 2009
Transfer Count: 2
Actual ARF Paid: \$30,057.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Nov 2024
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$19,565.00
COE Rebate Amount: \$6,195.00
Total Rebate Amount: \$6,195.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Apr 2023

OK