



Your Ref: S2M044P4

Date: 25th May 2023

Our Ref: CS3/ASM22005975/Dqp3m4-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard
#48-01 Marina Bay Financial Centre Tower 2
Singapore 018983
(The Motor Claims Department)

Attn: Khor Saw Theng

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFZ 536M
INSURED VEHICLE: SH 8096D
ACCIDENT DATE: 20/06/2022**

We thank you for your instruction on 18/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFZ 536M from Automax Survey.
- b) Singapore Accident Statement of Vehicles SFZ 536M and SH 8096D.
- c) Final Repair Bill of SFZ 536M from M/s Hup Ley Huat Motor Spray Painting Services.
- d) Colour damaged vehicle photographs of SFZ 536M.

Pre-Repair Inspection Date: 23/06/2022 at M/s Hup Ley Huat Motor Spray Painting Services, Blk 1 Kaki Bukit Ave 6, #01-35 Autobay, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SFZ 536M
Make & Model	: Honda Honda CRV 2.0L AT
Year of Registration	: 2009
Chassis Number	: JHLRE28309C200183
Engine Capacity	: 1997 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.