



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/HSB23001146/Rvp3-1

HSBC LIFE (SINGAPORE) PTE LTD  
10 MARINA BOULEVARD  
#48-01 MARINA BAY FINANCIAL CENTRE TOWER  
2SINGAPORE 018983

Ref: ~~CS3/HSB23001146/Rvp3~~  
Date: ~~06/02/2023~~ 17/05/2023  
Code: HSB

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SH 9645M	Veh. Inspected	FBQ 3109M
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04II9	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	<del>06/02/2023</del> 17/05/2023

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	27/01/2023	Inspection Date	06/02/2023
Survey held at	20 BUKIT BATOK CRESCENT #01-19, 658080		
Repairer	PRIMERO RACING		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.