



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

INCOME/LONPAC

DOA: 11/05/2023 @16.00

LONPAC INSURANCE BHD

15.5.2023

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:


GBG 2989 Z - NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

CHASSIS NO: VSKYBAM20Z0143510 (2017)

1 pc	Front bonnet <i>torn</i>	(nett)	\$	950.00
1 pc	Front bumper retainer RH <i>cn</i>	(nett)	\$	28.00
1 pc	Front bumper retainer LH <i>X NN</i>	(nett)	\$	28.00
1 pc	Front bumper reinforcement <i>lt</i>	(nett)	\$	1,183.00
1 pc	Front bumper sponge <i>cn</i>	(nett)	\$	326.00
1 pc	Front bumper top garnish RHS <i>de</i>	(nett)	\$	384.00
10 pcs	Front bumper clip @7.00 <i>ne</i>	(nett)	\$	70.00
1 pc	Front logo <i>cn</i>	(nett)	\$	97.00
	Front grille <i>ad</i>	n	\$	384.00
4 pcs	Front grille clip @7.00 <i>cn</i>	(nett)	\$	28.00
1 pc	Front support panel <i>repair X</i>	(nett)	\$	808.00
1 pc	Inter cooler <i>X NN RHS</i>	(nett)	\$	2,121.60
1 pc	Radiator side garnish LHS lower <i>de</i>	(nett)	\$	68.00
8 pcs	Radiator side garnish clip @7.00 <i>cn</i>	(nett)	\$	56.00
1 pc	Alternator <i>X NN</i>	(nett)	\$	1,555.00
			\$	8,154.60
		less: 10%	\$	815.46
			\$	7,339.14
6 pcs	Front bonnet sponge clip @7.00 <i>cn</i>		\$	42.00 30
1 pc	Front fender cowling RHS <i>torn</i>		\$	204.00
8 pcs	Front fender cowling RHS clips @7.00 <i>cn</i>		\$	56.00 30
1 pc	Front RH headlamp <i>cn</i>		\$	684.00
1 pc	Front bumper <i>de</i>		\$	653.00
1 pc	Front bumper foglight RHS <i>cn</i>		\$	340.00
1 pc	Front foglight bracket LHS <i>X NN</i>		\$	105.60
1 pc	Front bumper under cover <i>cn</i>		\$	279.80
			\$	9,703.54

Labour to jacking front inner panel, straight and straighten
front chasis and accident affected areas.

\$ ~~600.00~~
550



利 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Putty and spray painting on affected area front bonnet, front
RH fender, front bumper, inner panel and other parts affected
by accident.

\$	600.00	550
\$	10,903.54	

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....
Rasul
Hp 90010568
7 days
4/8
19/05/23 @ 1355
Resy after
repair

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: