

# 創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

INCOME/LONPAC

DOA: 11/05/2023 @16.00

LONPAC INSURANCE BHD

15.5.2023

ATTN: THE MOTOR CLAIMS DEPT


THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

GBG 2989 Z - NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

CHASSIS NO: VSKYBAM20Z0143510 (2017)

1 pc	Front bonnet	(nett)	\$	950.00
1 pc	Front bumper retainer RH	(nett)	\$	28.00
1 pc	Front bumper retainer LH	(nett)	\$	28.00
1 pc	Front bumper reinforcement	(nett)	\$	1,183.00
1 pc	Front bumper sponge	(nett)	\$	326.00
1 pc	Front bumper top garnish RHS	(nett)	\$	384.00
10 pcs	Front bumper clip @7.00	(nett)	\$	70.00
1 pc	Front logo	(nett)	\$	97.00
	Front grille	n	\$	384.00
4 pcs	Front grille clip @7.00	(nett)	\$	28.00
1 pc	Front support panel	(nett)	\$	808.00
1 pc	Inter cooler	(nett)	\$	2,121.60
1 pc	Radiator side garnish LHS lower	(nett)	\$	68.00
8 pcs	Radiator side garnish clip@7.00	(nett)	\$	56.00
1 pc	Alternator	(nett)	\$	1,555.00
			\$	8,154.60
		less: 10%	\$	815.46
			\$	7,339.14
6 pcs	Front bonnet sponge clip @7.00		\$	42.00
1 pc	Front fender cowling RHS		\$	204.00
8 pcs	Front fender cowling RHS clips @7.00		\$	56.00
1 pc	Front RH headlamp		\$	684.00
1 pc	Front bumper		\$	653.00
1 pc	Front bumper foglight RHS		\$	340.00
1 pc	Front foglight bracket LHS		\$	105.60
1 pc	Front bumper under cover		\$	279.80
			\$	9,703.54
	Labour to jacking front inner panel, straight and straighten front chasis and accident affected areas.		\$	600.00



# 創 CHARN'S CUSTOMCRAFT

*Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars*  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

Putty and spray painting on affected area front bonnet, front  
RH fender, front bumper, inner panel and other parts affected  
by accident.

\$	600.00
\$	<u>10,903.54</u>

Note: The above is an estimate only. IF other parts requested  
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....