

SM AUTOMOTIVE

Block C,1 Kaki Bukit Avenue 6 Blk C #01-43 Singapore 417883
 Email: SM_AUTOMOTIVE@HOTMAIL.COM
 Tel: (65) 6747 9241 Fax: (65) 6741 7276
 RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6
 # 01-43
 Singapore 417883
 Accident date : 12/05/2023

TP Chinn.
 Hiao Tony

15/05/2023

Estimated repair cost for vehicle no: SLT895L TOYOTA WISH 1.8 CVT
 CHASSIS: JTDGG20W70J007774 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR TAILGATE <i>Reyes</i>	\$1,315.20	\$1,315.20 +
2	1	REAR TAILGATE LOCK <i>and</i>	\$374.40	\$374.40 ✓
3	1	REAR TAILGATE INNER TRIM BOARD <i>new</i>	\$781.40	\$781.40 +
4	1	REAR TAILGATE EMBELM LOGO <i>3 m</i>	\$51.10	\$51.10 ✓
5	1	REAR TAILGATE EMBELM VALVE-MATIC ✓	\$84.70	\$84.70 ✓
6	1	REAR TAILGATE WINDSCREEN GLASS MOULDING <i>new</i>	\$136.40	\$136.40 +
7	1	REAR TAILGATE WEATHER STRIPE <i>lit</i>	\$187.20	\$187.20 ✓
8	1	REAR BUMPER <i>Delud</i>	\$625.50	\$625.50 ✓
9	1	REAR BUMPER REFLECTOR <i>RH could</i>	\$141.40	\$141.40 ✓ 36
10	2	REAR BUMPER BRACKET <i>new</i>	\$75.60	\$151.20 +
11	2	REAR BUMPER SIDE RETAINER <i>and</i>	\$132.10	\$264.20 85
12	1	REAR END PANEL <i>Delud</i>	\$612.50	\$612.50 ✓
13	1	REAR END PANEL TOP GARNISH <i>Delud</i>	\$375.40	\$375.40 286.
14	1	REAR END PANEL KEYLESS SENSOR <i>and</i>	\$186.40	\$186.40 ✓
15	1	REAR TAILLAMP <i>new</i>	\$699.40	\$699.40 +
16	1	REAR TAILLAMP LOWER BRACKET <i>new</i>	\$78.10	\$78.10 +

*R/H Rear fender Inner Trim Board.
 Delud - 434 ✓*

TOTAL : \$6,064.50
 LESS 25 % \$1,516.13
 SUB-TOTAL : \$4,548.38

*2982.80
 2237.10*

SLT895L TOYOTA WISH

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 30
2	1	REAR REVERSE SENSOR <i>new</i>	\$280.00	\$280.00 20
3	1	REAR TAILGATE WINDSCREEN GLASS SEALANT <i>new</i>	\$100.00	\$100.00 +
4	1	REAR END PANEL SEALANT <i>new</i>	\$60.00	\$60.00 -
5	2	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	\$60.00	\$120.00 30
6	1	REAR TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	\$80.00	\$80.00 +
7	1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	\$60.00	\$60.00 20

340

TOTAL: \$780.00

TOTAL PARTS: \$5,328.38

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,200.00	60
2	LABOUR FOR SPRAYPAINTING	\$1,000.00	100
3	WIRING CHECK	\$80.00	30
4	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	\$150.00	+
5	LABOUR FOR REMOVE & REFIX REAR UPHOSLTERY /ROOF LINING	\$300.00	40
6	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00	60
7	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	\$200.00	+

Subtotal :- \$3,230.00

Total:- \$8,558.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin Lj
c/s 15/05/23.

04 Dmp

Total 4007.10
w/s 3.2k.

3.2k