

Surveyor : RASUL LKK
 Claim : TP CHINA TAIPING
 DOA : 30.04.2023
 Emailed : 26.06.2023, 11.45am
 Date survey : 12.06.2023

VEHICLE NO : SMF 233 J
 MODEL : KIA CERATO 1.6 A SR SX
 WIP : 12767

Material	:	\$	<u>3,111.00</u>
Labour	:	\$	<u>1,690.00</u>
Sub-Total	:	\$	<u>4,801.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,801.00</u>
GST 8%	:	\$	<u>384.08</u>
Grand Total	:	\$	<u>5,185.08</u>
Finalise By/Date	:	<u>LOI / 26/06/2023</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 3 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 3

☒ TP claim GBF 4141 U

☐ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☒ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM KOK KHENG	Cust No/Name LCV06625/LIM KOK KHENG
49 SWISS VIEW	Reg No/Reg Date SMF233J*ECB / 21/09/2018
SINGAPORE 288055	Date In/Mileage 12/06/2023/ 72478
Contact No Mobile: 98326362	Chassis/Package KNAF3416MK5013617 /#
12/06/2023	Engine No G4FGJH703969
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/06/2023/ 11:26	TLK	260 / AiTing	12767

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 640.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 550.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 100.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 280.00
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR				✓ 100.00
M SUNDRY SUNDRIES				✓ 20.00
X LAMP ASSY-HEAD,RH	1.00	✓ 2210.00	00.00	2210.00
X COVER-FR BUMPER	1.00	✓ 665.00	00.00	665.00
X MOULDING-FRONT BUMPER,RH	1.00	✓ 90.00	00.00	90.00
X AIR DUCT-FR BUMPER,RH	1.00	✓ 14.00	00.00	14.00
X ABSORBER-FRONT BUMPER ENERGY	1.00	✓ 84.00	00.00	84.00
X ORNAMENT-KIA NO.115	1.00	✓ 38.00	00.00	38.00
X CLIP → <i>Supp</i>	10.00	1.00	00.00	10.00
Z TEXT TP CLAIM CHINA TAIPING GBF4141U DOA : 30.04.23 SURVEYOR RASUL-LKK 12.06.23 REPAIR 03 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,111.00	Nett	4,801.00
Labour	1,670.00	8% GST on	384.08
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	5,185.08
Sundry/Others	20.00		
Total(w/o GST)	4,801.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : CHINA TAIPING

Supplementary Parts For Registration No.: SMF 233 J

<u>Materials</u>		<u>Cost (\$)</u>
1	Clips (10)	10.00
Total		10.00
8% GST		0.80
Grand total		<u>\$ 10.80</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD


LOI AI TING
SENIOR OFFICER-ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240