




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG			Ref: CS3/HSB23005153/Tqp3e2 Date: 25/07/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8082A	Veh. Inspected	GBF 5197C
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04MK6	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	22/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDH2010208003	Colour	WHITE
	Odometer	200378 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	FARROAD	6 mm
	L/H Front Tyre	195 R15	FARROAD	6 mm
	R/H Rear Tyre	195 R15	FARROAD	6 mm
	L/H Rear Tyre	195 R15	FARROAD	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
5. General Information				
	Accident Date	14/05/2023	Inspect Date / Time	20/07/2023 (10:20 AM)
	Survey held at	SG ZOOM GARAGE PTE LTD 53 UBI AVENUE 1, #01-43, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/HSB23005153/Tqp3e2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.