

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 Blk C #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 09/05/2023

Estimated repair cost for vehicle no: SJA6440A BMW 523I A

CHASSIS: WBAFP320X0C866031 (2011)

15/05/2023

TP Chiam
Fzyan

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Reb</i>	\$1,298.50	\$1,298.50 ✓
2	1	FRONT BUMPER SPONGE <i>Auto</i>	\$398.80	\$398.80 135
3	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$585.80	\$585.80 +
4	1	FRONT BUMPER SENSOR <i>Buyd</i>	\$321.30	\$321.30 285
5	1	FRONT BUMPER SIDE BRACKET RH <i>new</i>	\$65.10	\$65.10 +
6	1	FRONT BUMPER FOG LAMP RH <i>Auto</i>	\$580.50	\$580.50 295
7	1	RH FRONT FENDER <i>new</i>	\$1,050.30	\$1,050.30 +
8	1	RH FRONT HEADLAMP <i>Auto</i>	\$2,392.10	\$2,392.10 ✓
9	1	RH FRONT HEADLAMP WIPER NOZZLER <i>new</i>	\$498.50	\$498.50 +

Front Bumper Fog Lamp Cover 110. ✓
Auto

TOTAL : \$7,190.90

LESS 5 % \$359.55

SUB-TOTAL : \$6,831.36

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 30

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without prejudice" basis
- No illegal modification is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

TOTAL: \$80.00

TOTAL PARTS : \$6,911.36

Labour charges

1	LABOUR FOR PANEL BEATING	by Repairer	300	\$600.00
2	LABOUR FOR SPRAYPAINTING		450	\$600.00
3	WIRING CHECK		30	\$80.00
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS		X	\$200.00

5 To remove front bumper sensor 100 50

6 To perform diagnostic test 150

Subtotal :- \$1,480.00

Total:- \$8,391.36

Admin Lj

17/05/23

03 Ryp

total 5269.82

h/s: 4.2K

4.2K