



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM23000782/Wnp3-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM23000782/Wnp3~~
Date: ~~20/01/2023~~ 22/05/2023
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 3676A	Veh. Inspected	SLL 2611T
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04IA3	Excess (\$)	0.00
Assign From	GARNET LOW	Assign Date	25/01/2023 22/05/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/01/2023	Inspection Date	30/01/2023
Survey held at	2 KAKI BUKIT AVENUE 2 #02-31 KAKI BUKIT AUTOHUB		
Repairer	CHENG CHUAN MOTOR SERVICES		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.