



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: GARNET LOW			Ref: CS3/ASM23000782/Wnp3m4-1 Date: 21/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 3676A	Veh. Inspected	SLL 2611T
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S3M04IA3	Excess (\$)	0.00
	Assign From	GARNET LOW	Assign Date	22/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MR053REH104558881	Colour	WHITE
	Odometer	211481 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	7 mm
	L/H Front Tyre	225/45 R17	MICHELIN	7 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	7 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/01/2023	Inspection Date	30/01/2023
	Survey held at	2 KAKI BUKIT AVENUE 2 #02-31 KAKI BUKIT AUTOHUB		
	Repairer	CHENG CHUAN MOTOR SERVICES		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	