

ASS. REC. BY:

REF:

17SB / 23005164/KP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$42k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGT 68251 Yr Regn: 04, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Honda Civic cc 1595

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 293858 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD45207S200392

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rlm / STD / A/Rlm or _____

Tyre Size: F: 205/55R16 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front R/Bal. 8 mm Rear R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 14/5/23 D.O.I. 1/6/2023

Survey held at _____

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/6	21 Rm @ 1000 Cash

Date/Time, File Pass to?

: Prel. Report

: Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____

S - RS. SI

Fixturs

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

HWA SENG SPRAY PAINTING PTE LTD

160 Sin Ming Drive
#05-11 Sin Ming Autocity
SINGAPORE 575722
(COMPANY REGISTRATION NO.: 202017045G)
TEL : 64533100
FAX : 62669932

Date of Accident: 14/05/2023

Your Insured
Vehicle No. : SH64821K

ESTIMATE REPAIR COSTS TO HONDA CIVIC REG. NO. : SGT 6825 J

		S\$
1pc	Headlamp	L 824.30 ✓
1pc	Front Bumper	R 783.90 ✗
		<hr/>
		1608.20
	Less : 20%	321.64
		<hr/>
		1286.56

LABOUR & MISC CHARGES

Panel Knocking	450.00 20d	
Spray Painting	500.00 40d	
Wire Checking	80.00 2d	
		<hr/>
TOTAL	2316.56	

*Not within
L1Rw @ 100d.
Delivery After Paint
2 days*

HWA SENG SPRAY PAINTING PTE LTD

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: