

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/111 23005171/4293

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA23912

at Workshop m/s PAUB,

of _____

Insured: SKT98237

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$69k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA23912 Yr Regn: 31/05/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / 402-01-5-EYESIGHT

Make: Subaru imparts c.c. 1995

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 54446 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF16K7KLSJG009282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. mm L/Bal. 6 mm

D.O.A. 24/03/23 D.O.I. 29/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 6/6/23 4/5 @ 1600 in Brand Ray

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

not Allowed
her
29/5/23
whole plate up -
3 days.
1/5 \$1600

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
IOB Building #04-05
Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department \ INDIA

Estimate No: EST1509513

Date: 24 Mar 2023

Policy No: PNPV2020-00005821-02

Veh Reg No: SMA2391Z

Make/Model: SUBARU IMPREZA 4D
2.0I-S EYESIGHT AWD
CVT

Your Ref No: TP 0323-7331

Claim Type: Third Party

Accident Date: 24/03/2023

TP Veh Reg No: SKT9823Y

Chassis No: JF1GK7KL5JG009282

Engine No: FB20YD89205

Reg. Date: 31/05/2018

Estimate Repair Cost to Vehicle No :SMA2391Z

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER	515.3000	1 PC	515.30	515.30
2 REAR BUMPER SIDE HOLDER - LH/RH	21.7000	2 PC	43.40	43.40
3 REAR BUMPER CLIPS	3.9000	10 PC	39.00	39.00
4 REAR BUMPER LOWER (BLACK)	0.0000	1 PC	0.00	0.00
5 REAR RIM - RH	997.2000	1 PC	997.20	997.20
			1,594.90	
		Less 20%	318.98	1,275.92
Special Net				
6 REAR TYRE - RH	280.0000	1 PC	280.00	280.00
			280.00	280.00
Labour				
7 TO KNOCK OUT DENTS ON FENDER, DOOR, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	800.00
8 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	800.00
9 TO CHECK WIRING	20.0000	1 JOB	20.00	20.00
10 TO 4 WHEEL ALIGNMENT	75.0000	1 JOB	75.00	75.00
11 TO REMOVE, REPLACE RIM & TYRE BALANCE	35.0000	1 JOB	35.00	35.00
			1,730.00	1,730.00
			Total	SS 3,285.92
			Add GST @ 8%	262.87
			Total Amount Payable	SS 3,548.79

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FIVE HUNDRED FORTY EIGHT AND CENTS SEVENTY NINE ONLY

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

1166
202
932.80
2012.8